



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	04 Dec 2022, 16:19:15
Transaction Number	52651181 (CC10009)	Queue Number	635536



Chassis Number	JTEBU25J475066585
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Prado
Model Year	2007
Color	White
Mileage	342693 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Engine Condition		
		المحرك
01.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,OIL LEAK REFITTED	حالة المحرك النظري
01.B Mount	MOUNT RUBBER CUT	كرسي
02 Transmission Condition		
		الجير
02.A Visual Gear Box Condition	NOT CHECKED ,OIL LEAK REFITTED	حالة الجير النظري
02.B Road Test	NOT CHECKED	فحص علي الطريق
02.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
03 Interior Condition		
		الحاله الداخليه
03.A AC Condition	NOT CHECKED	المكيف
03.B Door Panel	BOTH SIDE PORTION MELTED	لوحة بطانة الباب
03.C Dash Board	MELTED PORTION DAMAGED	لوحة القيادة
03.D Sun Visor	RIGHT SIDE PORTION LOOSE	حاجب الشمس
04 Tires and Rims Condition		
		الاطارات
04.A Rear Tyre	BOTH SIDE 2018 CRACKED	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2018 CRACKED	الاطار الامامي

DEFECT	REMARKS	
05 Body		جسم المركبة
05.A Paint	BODY PORTION REPAIRED REPAINTED , PORTION RUSTY ,MINOR DENTS SCRATCHES ON BODY	الصبغ
05.B Bonnet	SHOCK WEAK	غطاء المحرك
05.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
06 Suspension System		ممتص الصدمات
06.A Shock Absorber	LEAK	ممتص الصدمات
06.B Arms	LOWER ARM BUSHES CUT	ازرع
06.C Ball Joint	BOOT CUT	مفصل كروي
07 Steering Condition		المقود
07.A Steering Oil	OIL LEAK	زيت المقود
07.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
07.C Axle	BOOT CUT	اكسلات
07.D Steering Boot	BOOT CUT	ريلة المقود
08 Chassis Condition		الشاسي
08.A Chassis	FRONT RIGHT SIDE CHASSIS RUST BULGED ,BOTH SIDE THICK RUST PROOFED ,PORTION RUSTY	الشاسيه
09 Lights		الاضاءة
09.A Head Light	LENS FADED	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.