



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **25 May 2023, 11:16:59**  
 Transaction Number **55995080 (CC10013)** Queue Number **726273**



Chassis Number **JMYLRV73W6J706232**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Mitsubishi**  
 Model **Pajero**  
 Model Year **2006**  
 Color **Grey**  
 Mileage **266500 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **6**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Chassis Condition</b>		<b>الشاسي</b>
01.A Chassis	NOT CHECK	الشاسيه
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Visual Engine Condition	OIL LEAK	حالة المحرك النظري
02.B Smoke	WHITE	دخان
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Floor	UNDER FLOOR CHASSIS SUSPENSION PARTS NOT CHECK	الارضيه
03.B Other	VISUAL TEST ONLY	اخرى
03.C Bumper	MISALIGN GETTING FADED & EXTRA BULLBAR	دعامية
03.D Paint	BODY PORTION REPAINTED PORTION REPAIRED PORTION FADED MINOR DENT SCRATCHES	الصبغ
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
04.B AC Condition	NOT WORKING PROPERLY GRILL WORN OUT	المكيف
04.C Roof Ceiling	PORTION LOOSE	بطانه السقف
<b>05 Lights</b>		<b>الاضاءة</b>

DEFECT	REMARKS	
05.A Head Light	LENS FADED ALL LIGHT NOT CHECK	الاضاءة الرئيسية
<b>06 Brake Condition</b>		<b>الفرامل</b>
06.A Disc&Drum	RUSTY	دسك وطيناير الفرامل
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Visual Gear Box Condition	NOT CHECK	حالة الجير النظري
<b>08 Seats Condition</b>		<b>المقاعد</b>
08.A Seat Condition	PORTION DAMAGED	حالة المقاعد
<b>09 Tires and Rims Condition</b>		<b>الاطارات</b>
09.A Front Tyre	DRY CRACK WORN OUT	الاطار الامامي
09.B Rear Tyre	DRY CRACK WORN OUT	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.