



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>19 Aug 2022, 10:42:30</b>
Transaction Number	<b>89500995 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JTFPX22P4J0085689</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Hiace</b>
Model Year	<b>2018</b>
Color	<b>White</b>
Mileage	<b>40220 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	OK	المكيف
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Front Tyre	BOTH SIDE 2018 & CRACKED	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2018 & CRACKED	الاطار الخلفي
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	SIGN OF MINOR OIL LEAK	حالة الجير النظرى
<b>04 Body</b>		<b>جسم المركبة</b>
04.A Trunk	PORTION REPAIRED,REPAINTED	صندوق
04.B Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
04.C Sign of front accident		وجود مؤشر لحادث في المقدمة
04.D Other	FRONT RIGHT SIDE CRASH BOX & BACK PANEL , CROSS MEMBER REPAIRED	اخرى
04.E Sign of back accident		وجود مؤشر لحادث في الخلف

DEFECT	REMARKS	
04.F Bonnet	PORTION REPAINTED	غطاء المحرك
<b>05 Suspension System</b>		<b>ممتص الصدمات</b>
05.A Arms	CONTROL ARM BUSHES CRACKED	ازرع
05.B Leaf Spring	LEAF SPRING BUSHES WORN OUT	
05.C Ball Joint	BOOT CUT	مفصل كروي
<b>06 Chassis Condition</b>		<b>الشاصي</b>
06.A Chassis	OK	الشاسيه
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	SIGN OF MINOR OIL LEAK	حالة المحرك النظري
07.B Smoke	MINOR BLACK SMOKE	دخان

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.