



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	16 Sep 2021, 12:00:21
Transaction Number	69370718 (CC10006)	Queue Number	312309



Chassis Number	PNK15Z516388
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	1997
Color	Green
Mileage	16179

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY PORTION REPAIRED , REPAINTED & DENTS ,SCRATCHES, RUSTY ON BODY	الصبغ
01.C Doors	PORTION REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS , FLOORING, CHASSIS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR, WHEEL HOUSING, QUATER PANEL, RUNNING BOARD RUSTY & WEAK	الارضية
01.F Bonnet	REPAINTED	غطاء المحرك
01.G Roof	REPAIRED, REPAINTED & RUSTY, WEAK & DAMAGED, CRACKED	السقف
01.H Other	FRONT FENDER FRAME, BUMPER FRAME, CROSSMEMBER , BULKHEAD & REAR CROSSMEMBER, BACK PANEL, QUATER PANEL REPAIRED	اخرى
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS FRAME COMPLETLY RUST & MIDDLE INNER DENT	الشاسيه
02.B Other	VIN NUMBER AREA RUSTY NOT VISABLE CHECK ONLY ON PLATE	اخرى
02.C Chassis Extension	REAR RIGHT SIDE REPAIRED, DENT OLD	تمديدات الشاسي
03 Seats Condition		المقاعد
03.A Other	OK	اخرى

DEFECT	REMARKS	
04 Engine Condition		المحرك
04.A Other	MINOR OIL LEAK	اخرى
04.B Smoke	WHITE SMOKE	دخان
05 Transmission Condition		الجير
05.A Gear Box	OIL LEAK	الجير
05.B Gear Box Mount	BUSHES CRACKED	كرسي الجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2011 CRACKED & EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2011 CRACKED & EXPIRED	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	NOT WORKING PROPERLY	اخرى
08 Lights		الاضاءة
08.A Head Light	HIGH BEAM & LOW BEAM NOT WORKING	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
10 Suspension System		ممتص الصدمات
10.A Leaf Spring	BOTH SIDE BUSHES CUT & LEAF GETTING RUSTY	
10.B Shock Absorber	WEAK & LEAK	ممتص الصدمات
11 Interior Condition		الاجزاء الداخلية
11.A Other	INNER ROOF RUSTY & COVER MISSING	اخرى
11.B Mirror	OK	المرايا
11.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



X FAILED

Plate Details :	--
Chassis No :	PNK15Z516388
Vehicle Make :	NISSAN
Vehicle Model :	PATROL
Vehicle Class :	Light Vehicle
Body Type :	JEEP
Fuel :	Benzene
Color :	Green, Golden
Drive Direction :	--
Dimensions : (H x W x L) --x--x--	
Current Odometer :	16181 Kms.
Origin :	Japan
Model Year :	1997
Gear Type :	--
Engine Size :	2500 CC
Engine No :	46M1001
Horse Power :	--
Axles No :	2
Cylinders :	4
No Of Doors :	2
No Of Seats :	6
G. V. W. :	2000 Kgs.
Empty Weight :	1600 Kgs.

Certificate Number :	5-TAS-2021-15185135
Inspection Date :	07-10-2021
Certificate Print Date :	07-10-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	7 min 30 sec
Appointment Ref Number :	--
Start Time :	14:54
End Time :	15:02
Lane :	04
Token No. :	174
Attempt :	2
Prints No. :	1

Inspection Findings

Defects	Issue	Severity
Springs (leaf/coil) and shackle pin change rear both leaf spring bush wornout	Worn-out bushes	Major
Spare Tire	Missing (Major)	Major
Park and Tail lamps both tail light lens faded	Lens cracked, broken or faded (Major)	Major
Frame (Body) repair all rusty portion	Rusted/corroded frame	Major
Park and Tail lamps front & rear both park light not working	Defective	Major
Gear/Differential repair front differential oil leak	Oil leaking continuously	Major
Vehicle Floor repair all rusty portion underneath	Others (Major)	Major
Tire change all tire old	Date of manufactured tampered or expired	Major
Doors and Locks open rear door for recheck	Others (Major)	Major
Dip beams(Low Beams) headlight both head light not working	Defective	Major
Wiper arms, Blades, Washer repair wiper	Damaged or bend wiper arm(s) (Major)	Major
Stop lamps left & center brake light not working	Defective	Major
Chassis clean scrape to metal chassis frame for recheck	Others (Major)	Major
Rear registration plate lamps	Missing	Major
Reversing lamps REVERSE LIGHT NOT WORKING	Defective	Major
Engine repair engine smoke	Excessive oil smoke	Major

Inspection Remarks:

vin number re punched ok as per rta letter /engine & gear minor oil leak//rear right chassis end & cross member dent & welded repaired

Payment Details

Inspection Performed by Payment Method Transaction Number Service Fees