CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2944986
Transaction Date	06 Nov 2026, 16:08:31
Site Name	840 - Emirates Auctions
Transaction Number	30296876 (CC10013) (CC10013)



Vehicle Details

Chassis Number	3FAHP0GA0C*******
Specification	Imported
Make	Ford
Model	Fusion
Model Year	2012
Color	Red
Mileage	152887 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION CRACK	دعامية
01.E Trunk	NOT CHECKED	صندوق
01.F Fuel Tank	DENT	خزان الوقود
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS MUDDY DIRTY PORTION GETTING RUSTY / CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED OIL LEAK . PARTS RUSTY ABNORMAL NOISY	الحالة النظريه للمحرك
04 Exhaust System		نظام العادم
04.A Other	DENT	اخري
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2025 BOTH SIDE	الاطار الامامي
06.B Rear Tyre	2022 BOTH SIDE	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	PORTION CRACK	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	LOWER ARM BUSHES CUT	ازرع
08.C Ball Joint	BOOT CUT	مفصل كروي
08.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودات
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED	اخري
10.B AC Condition	NOT WORKING	المكيف
10.C Power Window Switch And Glass	SWITCH BUTTON NOT WORKING PROPERLY	مفتاح النافذه و الزجاج
10.D Dash Board	GETTING FADED PORTION WORN OUT	لوحة القياده
10.E Roof Ceiling	PORTION WORN OUT GRAB HANDLE NOT WORKING	بطانه السقف
10.F Sun Visor	LOOSE	حاجب الشمس
10.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	WATER EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae