



Test Certificate

| | | | |
|---------------------|------------------------|--------------------|---------------|
| Site Number | : 756-SHJ AUTO VILLAGE | Plate Code | : |
| Transaction Number | : 20131564 | Plate Category | : |
| Transaction Date | : 04 JUL 2020 13:33:58 | Plate Number | : |
| Queue Number | : 192435 | Import Doc. Ref. | : 00920 EA |
| Chassis Number | : 19XFB2625EE900920 | Manufacturer/Model | : HONDA/CIVIC |
| Engine Number | : | Model Year | : 2014 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : BLACK |
| Service / Indicator | : DSC AUCTION | Mileage | : 179788 |

Statement of Vehicle Condition

| Defect | Result | Remarks |
|--|--------|----------------------------------|
| AUTOMATIC TEST: | | |
| 13 Brake System | | الفرامل |
| 13.04 - Brake Test | Passed | فحص الفرامل |
| 14 Exhaust Gas Test | | الغاز العادم والكربون |
| 14.01 - Exhaust Gas Test | Passed | فحص الغاز العادم-الكربون |
| 17 Shock Absorbers Test | | فحص مخمد الصدمات |
| 17.01 - Shock Absorber Test | Passed | فحص مخمد الصدمات |
| VISUAL TEST: | | |
| 04 Tires Rims | | الاطارات والعجلات |
| 04.01 - Front Left And Right Hands Tires | | الاطارات الامامية |
| | | ALL TYRES CRACKED WEAK OLD 2016. |
| 05 Body | | الهيكل |
| 05.02 - Paint | | الصبغ |
| 05.05 - Bumpers | | الدعامية |
| | | MINOR BODY BUMPERS SCRATCHES. |
| | | FRONT BUMPER REFITTED. |
| 06 General Items | | الاشياء العامة |
| 06.21 - Battery Condition | | حالة البطارية |
| | | UNSECURE,CLAMP MISSING. |
| 09 Auction | | الفحص الكامل |
| 09.06 - Chassis Ok | OK | التشاصي جيد |
| 09.09 - Engine And Gear Box Performance Ok | OK | فحص حالة الماكينة والجير |

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط
تسجيل غير مسئولة عن العيوب الخفية