



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **09 Nov 2022, 16:59:41**
 Transaction Number **56762842 (CC10009)** Queue Number **620120**



Chassis Number **6T1BF9FK7FX556598**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Toyota**
 Model **Camry**
 Model Year **2015**
 Color **Silver**
 Mileage **86248 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Transmission Condition الجير		
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	MINOR OIL LEAK,REFITTED	حالة الجير النظرى
02 Body جسم المركبة		
02.A Paint	BODY REPAINTED PORTION REPAIRED MINOR DENTS SCRATCHES	الصبغ
02.B Sign of side accident		وجود مؤشر لحادث في الجانب
02.C Pillars	RIGHT SIDE B/PILLAR ,ROCKER PANEL,DOOR POST REPAIRED	القوائم
02.D Bumper	MISALIGN	دعامية
02.E Fenders	REFITTED	مدكار
02.F Bonnet	REFITTED	غطاء المحرك
02.G Sign of front accident		وجود مؤشر لحادث في المقدمة
02.H Sign of back accident		وجود مؤشر لحادث في الخلف
02.I Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخرى
03 Tires and Rims Condition الاطارات		

DEFECT	REMARKS	
03.A Front Tyre	BOTH SIDE 2020,	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2020,	الاطار الخلفي
04 Interior Condition		الحالة الداخليه
04.A Power Window Switch	FRONT RIGHT SIDE NOT WORKING OWN SWITCH,SWITCH LOOSE	مفتاح النافذه
04.B AC Condition	REAR AIR FLOW LOW	المكيف
04.C Mirror	ADJUSTMENT NOT WORKING PROPERLY	المرايا
04.D Sun Visor	STAND LOOSE	حاجب الشمس
05 Seats Condition		المقاعد
05.A Seat Belt	REAR RIGHT SIDE NOT WORKING	حزام الأمان
06 Engine Condition		المحرك
06.A Visual Engine Condition	MINOR OIL LEAK,REFITTED	حالة المحرك النظري
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSH CRACKED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
09 Chassis Condition		الشاصي
09.A Chassis	REAR RIGHT SIDE CHASSIS EXTENSION END OUTER REPAIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



✓ PASS

Plate Details :	--
Chassis No :	6T1BF9FK7FX556598
Vehicle Make :	TOYOTA
Vehicle Model :	CAMRY
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Silver
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	86250 Kms.
Origin : Australia	Model Year : 2015
Gear Type : Automatic	Engine Size : 2500 CC
Engine No : U185756	Horse Power : 178
Axles No : 2	Cylinders : 4
No Of Doors : 4	No Of Seats : 5
G. V. W. : 2000 Kgs.	Empty Weight : 1500 Kgs.

Certificate Number :	5-TAS-2022-18162604		
Inspection Date :	23-11-2022		
Certificate Print Date :	23-11-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	9 min 27 sec		
Appointment Ref Number :	--		
Start Time :	11:18	End Time :	11:28
Lane :	01	Token No. :	127
Attempt :	2	Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Vehicle Consumption (last 12 Months)

1026 KM	106 L	362 AED	0.3 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Inspection Remarks: front bumper,bulk head,fender frame,rear panel,quarter panel,fender,wheel arch,rear right c pillar repaired.

Payment Details

Inspection Performed by 3104	Payment Method Cash	Transaction Number 18162604	Service Fees AED 70 Collected on 23/11/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Bajurdeen Abdul Gafoor

① This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

② Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصيرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

