



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>10 Aug 2022, 13:16:56</b>
Transaction Number	<b>65719905 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WVWEH21KOAW129848</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Volkswagen</b>
Model	<b>Golf</b>
Model Year	<b>2010</b>
Color	<b>White</b>
Mileage	<b>196435 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Lights</b>		<b>الاضاءة</b>
01.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
02.C Visual Gear Box Condition	MINOR OILLEAK,JERKING	حالة الجير النظرى
<b>03 Chassis Condition</b>		<b>الشاصي</b>
03.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Smoke	MINOR BLACK SMOKE	دخان
04.B Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظرى
04.C Mount	MOUNT RUBBER CRACKED	كرسي
<b>05 Interior Condition</b>		<b>الحاله الداخليه</b>
05.A Other	CENTER CONSOLE BOX SIDE WORN OUT	اخرى
05.B AC Condition	OK	المكيف

DEFECT	REMARKS	
<b>06 Body</b>		<b>جسم المركبة</b>
06.A Fenders	FRONT RIGHT SIDE & REAR BOTH SIDE PORTION REPAIRED,REPAINTED	مدكار
06.B Doors	FRONT RIGHT SIDE & REAR BOTH SIDE PORTION REPAIRED,REPAINTED	أبواب
06.C Bonnet	PORTION REPAIRED,REPAINTED	غطاء المحرك
06.D Trunk	PORTION REPAIRED,REPAINTED,REFITTED	صندوق
06.E Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
06.F Roof	PORTION REPAIRED,REPAINTED	السقف
06.G Bumper	MISALIGN	دعامية
06.H Pillars	RIGHT SIDE PILLAR OUTER PANEL PORTION REPAIRED,REPAINTED	القوائم
06.I Floor	UNDER FLOOR FINDER CHASSIS FULLY COVERED CHECKED VISIBLE AREA	الارضية
<b>07 Tires and Rims Condition</b>		<b>الاطارات</b>
07.A Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
07.B Front Tyre	BOTH SIDE 2019	الاطار الامامي
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Arms	LOWER ARM BUSHES CRACKED	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
<b>09 Seats Condition</b>		<b>المقاعد</b>
09.A Seat Condition	DRIVER SEAT PORTION DAMAGED	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.