CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877887
Transaction Date	20 Oct 2026, 10:42:05
Site Name	840 - Emirates Auctions
Transaction Number	10109070 (CC10021) (CC10019)



Vehicle Details

Chassis Number	SALFA24AX8*******
Specification	GCC Specification
Make	Land Rover
Model	LR2-HSE
Model Year	2008
Color	Grey
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES ,PORTION RUSTY PORTION FADED .	الصبغ
01.B Floor	UNDER FLOOR,SUSPNSION NOT CHECK	الارضية
01.C Bumper	MISALIGN PORTION DAMAGED.	دعامية
01.D Other	(VISUAL INSPECTION ONLY)	اخري
02 Chassis Condition		الشاصي
02.A Chassis	NOT CHECKED	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECK	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACKED	الاطار الامامي

Condition	Remarks	الحالة
06.B Rear Tyre	BOTH SIDE 2022 CRACKED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED,ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS RUSTY WATER FLOODED	اخري
08.B AC Condition	NOT CHECKED	المكيف
08.C Dash Board	PORTION CRACKED DAMAGED,MELTED	لوحة القياده
08.D Roof Ceiling	PORTION LOOSE	بطانه السقف
08.E Odometer reading	NOT CHECKED	قراءة عداد المسافات
08.F Door Panel	PORTION DAMAGED .LOOSE	لوحة بطانة الباب
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.H Gear Shifting Lever	DUST COVER DAMAGED & KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**