CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899712
Transaction Date	27 Oct 2026, 13:00:55
Site Name	840 - Emirates Auctions
Transaction Number	78521190 (CC10010) (CC10011)



Vehicle Details

Chassis Number	1N4AL3AP6D*******
Specification	Imported
Make	Nissan
Model	Altima
Model Year	2013
Color	Black
Mileage	215661 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED,REAR RIGHT REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Doors	FRONT BOTH SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN,PORTION DAMAGED,LOGO MISSING	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.H Pillars	LEFT SIDE A/PILLAR OUTER PANEL REPAIRED	القوائم
01.I Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASISS CVERED ,RIGHT SIDE OUTER SKIRT DENT ,REAR EXTENSION END DENT .	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	BLACK	دخان
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		**الاضاءة**
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Brake Condition		**الفرامل**
07.A Brake Pedal	SPONGY	دواسة الفرامل
07.B Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Interior Condition		**الحاله الداخليه**
08.A AC Condition	NOT COOLING	المكيف
08.B Roof Light	ASSEMBLY LOOSE	أنارة السقف
08.C Power Window Switch And Glass	FRONT LEFT SIDE NOT WORKING	مفتاح النافذه و الزجاج
08.D Dash Board	TRUNK SWITCH ASSEMBLY LOOSE	لوحة القياده
08.E Sun Visor	LOOSE	حاجب الشمس
08.F Door Panel	PORTION WORN OUT LOOSE	لوحة بطانة الباب
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae