



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	09 May 2022, 17:04:54
Transaction Number	95540286 (CC10006)	Queue Number	312309



Chassis Number	KNDJP3A58E7004808
Engine Number	
Vehicle Class	Car
Manufacturer	Kia
Model	Soul
Model Year	2014
Color	Grey
Mileage	001 Miles
Fuel Type	Petrol
No. Of Cylinders	4
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY MINOR DENT ,SCRATCHES & PORTION PAINT DAMAGED	الصبغ
01.B Windshield	FRONT CRACKED	زجاج
01.C Other	COWL PANNEL COVER & FUES BOX BURN	اخرى
01.D Pillars	RIGHT SIDE B/PILLAR MINOR DENT	القوائم
02 Engine Condition		المحرك
02.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK	حالة المحرك النظري
02.B Other	ENGINE PARTS BURN & DAMAGED	اخرى
03 Lights		الاضاءة
03.A Head Light	BURN	الاضاءة الرئيسية
03.B Other	ALL LIGHTS NOT CHECK	اخرى
04 Interior Condition		الحاله الداخليه
04.A AC Condition	NOT CHECK	المكيف
04.B Mirror	VIEW MIRROR MISSING	المرآيا
04.C Odometer reading	NOT CHECK	قراءة عداد المسافات

DEFECT	REMARKS	
05 Transmission Condition		الجير
05.A Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2017 EXPIRED , CRACKED , WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2017 EXPIRED , CRACKED	الاطار الخلفي
07 Chassis Condition		الشاسي
07.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.