



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>30 Nov 2022, 12:22:20</b>
Transaction Number	<b>76200624 (CC10009)</b>	Queue Number	<b>634445</b>



Chassis Number	<b>LSJA36E38LZ039306</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>MG</b>
Model	<b>5</b>
Model Year	<b>2020</b>
Color	<b>Grey</b>
Mileage	<b>001 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Engine Condition</b>		
		<b>المحرك</b>
01.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,KEY MISSING,	حالة المحرك النظرى
01.B Mount	MOUNT RUBBER CRACKED	كرسي
<b>02 Transmission Condition</b>		
		<b>الجير</b>
02.A Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
02.B Visual Gear Box Condition	NOT CHECKED	حالة الجير النظرى
02.C Road Test	NOT CHECKED	فحص علي الطريق
<b>03 Chassis Condition</b>		
		<b>الشاسي</b>
03.A Chassis	OK	الشاسيه
<b>04 Tires and Rims Condition</b>		
		<b>الاطارات</b>
04.A Front Tyre	BOTH SIDE 2019,	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2019,	الاطار الخلفي
<b>05 Body</b>		
		<b>جسم المركبة</b>
05.A Paint	BODY MINOR DENT,SCRATCHES,	الصبغ



- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.