

Queue Number 2756566

Transaction Date 17 Sep 2026, 11:54:09

Site Name
840 - Emirates AuctionsTransaction Number
13408509 (CC10009) (CC10012)

Vehicle Details

Chassis Number	JM7GL4S30M*****
Specification	GCC Specification
Make	Mazda
Model	6
Model Year	2021
Color	Black
Mileage	80442 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE , REAR BOTH SIDE REPAINTED PORTION REPAIRED , FRONT LEFT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT LEFT SIDE , REAR BOTH SIDE REPAINTED PORTION REPAIRED , LEFT SIDE BOTH REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS NOT VISIBLE	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	PORTION REPAINTED PORTION REPAIRED	غطاء المحرك
01.H Pillars	LEFT SIDE PILLAR ROCKER PANEL REPAIRED , B / PILLAR DENT	القوائم
01.I Trunk	REPAINTED PORTION REPAIRED , MISALIGN	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS COVERED, CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	REMOVE ALL UNDER COVER FOR RECHECK PROPERLY	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK PARTS REFITTED ,GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	MINOR OIL LEAK PARTS REFITTED	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06 Interior Condition		الحالة الداخلية
06.A Other	INNER PARTS GETTING RUSTY, SIGN OF FLOODED	اخرى
06.B Mirror	LEFT SIDE FOLDING NOT WORKING , LOOSE	المرآيا
06.C AC Condition	OK	المكيف
06.D Odometer reading	DISPLAY PANEL PORTION LOOSE	قراءة عداد المسافات
06.E Door Panel	MINOR WORN OUT	لوحة بطانة الباب
07 Battery Condition		حالة البطارية
07.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae