CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2873096
Transaction Date	15 Oct 2026, 12:53:17
Site Name	840 - Emirates Auctions
Transaction Number	80303078 (CC10013) (CC10019)



Vehicle Details

Chassis Number	JN8BY2NY4H*******
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2017
Color	Grey
Mileage	313260 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES ,PORTION FADED,PORTION RUSTY	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR RUST PROOFED	الارضية
01.F Bumper	PORTION FADED	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Trunk	REPAINTED PORTION REPAIRED & SWITCH NOT WORKING PROPERLY	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETELY THICK RUST PROOFED PORTION GETTING RUSTY	الشاسيه
03 Engine Condition		المحرك
03.A Other	ELECTRIC WIRE WORN OUT UNSAFE	اخري
03.B Engine Visual Condition	OIL PAN DENT , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION CUT & ADJUSTMENT NOT WORKING PROPERLY	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Wipers and Arms		المساحات
06.A Wiper Arm &Blade	BOTTLE CAP MISSING	ازرع المساحات والشفرات
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUSHES DRY CRACK	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Steering Condition		المقود
08.A Steering Boot	BOOT LEAK	ربلة المقود
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخري
09.B Mirror	CENTER MIRROR PORTION LOOSE	المرايا
09.C AC Condition	OK	المكيف
09.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.E Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae