



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 10 May 2022, 16:50:30 |
| Transaction Number | 22572595 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | SALLMAM348A294176 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Range Rover |
| Model | Sport |
| Model Year | 2008 |
| Color | Silver |
| Mileage | 130253 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 8 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------------|--|------------------------|
| 01 Interior Condition | | الحاله الداخليه |
| 01.A AC Condition | NOT COOLING | المكيف |
| 01.B Dash Board | PORTION CRACKED | لوحة القيادة |
| 02 Body | | جسم المركبة |
| 02.A Bonnet | REPAIRED , REPAINTED , REFITTED , PULLING CABLE NOT BROKEN | غطاء المحرك |
| 02.B Roof | ROOF RAILL ROOF PORTION REPAINTED | السقف |
| 02.C Fenders | REPAINTED , PORTION REPAIRED | مدكار |
| 02.D Paint | BODY PORTION REPAINTED , PORTION REPAIRED ,MINOR DENTS SCRATCHES ON BODY | الصبغ |
| 02.E Doors | LEFT SIDE DOOR PORTION REPAINTED | أبواب |
| 03 Tires and Rims Condition | | الاطارات |
| 03.A Front Tyre | BOTH SIDE 2019 | الاطار الامامي |
| 03.B Rear Tyre | BOTH SIDE 2019 | الاطار الخلفي |
| 04 Lights | | الاضاءة |
| 04.A Warning Light | WARNING LIGHT ON DISPLAY | ضوء تحذير |
| 04.B Tail Light | REAR LEFT SIDE COVER CRACKED | الانارة |

| DEFECT | REMARKS | |
|----------------------------------|--------------------------------|---------------------|
| 05 Engine Condition | | المحرك |
| 05.A Visual Engine Condition | SIGN OF MINOR OIL LEAK , | حالة المحرك النظري |
| 06 Transmission Condition | | الجير |
| 06.A Road Test | NOT CHECKED | فحص علي الطريق |
| 06.B DIFFERENTIAL | OIL LEAK, | الدفرنشل |
| 06.C Visual Gear Box Condition | MINOR OIL LEAK | حالة الجير النظري |
| 06.D Gear Box Mount | MOUNT RUBBER MINOR CRACKED | كرسي الجير |
| 07 Suspension System | | ممتص الصدمات |
| 07.A Arms | LOWER ARM BUSHES MINOR CRACKED | ازرع |
| 07.B Ball Joint | BOOT CUT | مفصل كروي |
| 08 Steering Condition | | المقود |
| 08.A Axle | BOOT CUT | اكسلات |
| 08.B Tie Rod End | BOOT CUT | مؤخرة الرودادات |
| 09 Chassis Condition | | الشاسي |
| 09.A Chassis | OK | الشاسيه |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.