CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934218	Transaction Date	02 Nov 2026, 14:29:05
Site Name	840 - Emirates Auctions	Transaction Number	21305774 (CC10026) (CC10026)



Vehicle Details

Chassis Number	5NPEL4JA0M*******
Specification	Imported
Make	Hyundai
Model	Sonata
Model Year	2021
Color	Silver
Mileage	105188 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED	الصبغ
01.C Floor	UNDER FLOOR COVERED PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN	دعامية
01.E Trunk	PORTION REPAINTED , REFITTED	صندوق
01.F Sign of back accident	BACK PANEL, QUATER PANEL, COMPARTMENT REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis Extension	BOTH SIDE CHASSIS EXTENSION REPAIRED , DENT	تمديدات الشاسي
02.B Chassis	CHASSIS COVERED MUDDY , CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	REFITTED PARTS GETTING RUSTY , SIGN OF OIL WET ,ABNORMAL NOISY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	REFITTED PARTS GETTING RUSTY , SIGN OF OIL WET	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	WARNING LIGHT ON DISPLAY	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخري
09.B AC Condition	OK	المكيف
09.C Dash Board	PORTION WORN OUT	لوحة القياده
09.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
09.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	COOLANT MIX WITH OIL	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae