

Queue Number 2643007

Transaction Date 13 Aug 2026, 10:43:37

Site Name
840 - Emirates AuctionsTransaction Number
76162408 (CC10008) (CC10012)

Vehicle Details

Chassis Number	LZWADAGAXN*****
Specification	GCC Specification
Make	Chevrolet
Model	Captiva
Model Year	2022
Color	White
Mileage	64095 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		
01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED ,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED DENTS SCRATCHES , PORTION GETTING RUSTY	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS ,POWER TRAIN GETTING RUSTY ,SIGN OF WATER FLOODED	صدأ
01.D Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.E Sign of front accident		وجود مؤشر لحادث في المقدمة
02 Chassis Condition		
02.A Chassis	CHASSIS PORTION GETTING RUSTY / OK	الشاسيه
03 Engine Condition		
03.A Engine Visual Condition	COMPONENTS RUSTY	الحالة النظرية للمحرك
04 Seats Condition		
04.A Seat Condition	DRIVER SEAT SIDE COVER LOOSE	حالة المقاعد
05 Transmission Condition		
05.A Gear Box Visual Condition	COMPONENTS RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY	دسك و طنابير الفرامل
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY ,CENTER CONSOLE BOX COVER LOOSE	اخرى
08.B Mirror	SIDE MIRROR FOLDING NOT WORKING ,CENTER MIRROR COVER MISSING ,HOLDER REPAIRED	المرآيا
08.C AC Condition	OK	المكيف
08.D Roof Ceiling	PORTION DAMAGED ,FRONT RIGHT SIDE GRAB HANDLE DAMAGED	بطانة السقف
08.E Sun Visor	LEFT SIDE BRACKET DAMAGED	حاجب الشمس
08.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.G Gear Shifting Lever	DUST COVER WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae