



### Test Certificate

|                     |                        |                    |                     |
|---------------------|------------------------|--------------------|---------------------|
| Site Number         | : 840-EMIRATES AUCTION | Plate Code         | : 0                 |
| Transaction Number  | : 19680580             | Plate Category     | : PRIVATE           |
| Transaction Date    | : 26 APR 2020 11:09:36 | Plate Number       | : 705975 EA         |
| Queue Number        | : 167764               | Import Doc. Ref.   | :                   |
| Chassis Number      | : JMYSRCS1AAU705975    | Manufacturer/Model | : MITSUBISHI/LANCER |
| Engine Number       | :                      | Model Year         | : 2010              |
| Vehicle Class       | : LIGHT VEHICLE        | Vehicle Color      | : SILVER            |
| Service / Indicator | : DSC AUCTION          |                    |                     |

### Statement of Vehicle Condition

| Defect                                   | Result | Remarks                                                             |
|------------------------------------------|--------|---------------------------------------------------------------------|
| <b>AUTOMATIC TEST:</b>                   |        |                                                                     |
| 13 Brake System                          |        | الفرامل                                                             |
| 13.04 - Brake Test                       | Passed | فحص الفرامل                                                         |
| 14 Exhaust Gas Test                      |        | الغاز العادم والكربون                                               |
| 14.01 - Exhaust Gas Test                 | Passed | فحص الغاز العادم-الكربون                                            |
| 16 Side Slip Test                        |        | فحص ميزانية الاطارات                                                |
| 16.01 - Side Slip Test                   | Passed | فحص ميزانية الاطارات                                                |
| 17 Shock Absorbers Test                  |        | فحص مخمد الصدمات                                                    |
| 17.01 - Shock Absorber Test              | Passed | فحص مخمد الصدمات                                                    |
| <b>VISUAL TEST:</b>                      |        |                                                                     |
| 01 Lights                                |        | الانوار                                                             |
| 01.06 - Brake Lights                     |        | RIGHT SIDE NOT WORK<br>أنوار الفرامل                                |
| 02 Steering And Suspension System        |        | عجلة القيادة ونظام التوصيلات                                        |
| 02.16 - Engine Mounting                  |        | MOUNTING CRACK<br>كراسي المحرك                                      |
| 03 Brake System                          |        | نظام الفرامل                                                        |
| 03.05 - Brake Pedal                      |        | SPONGY<br>دواسة الفرامل                                             |
| 04 Tires Rims                            |        | الاطارات والعجلات                                                   |
| 04.01 - Front Left And Right Hands Tires |        | TIRES 2014 & 2016<br>الاطارات الامامية                              |
| 04.07 - Rims                             |        | REAR RIGHT RIMS DENT<br>الرنجات                                     |
| 04.08 - Spare Tires                      |        | PUNCTURE<br>الاطار الاحتياطي                                        |
| 05 Body                                  |        | الهيكل                                                              |
| 05.05 - Bumpers                          |        | FRONT BUMPER SUPPORT FRAME BEND<br>الدعامية                         |
| 05.07 - Floor                            |        | MIDDLE REINFORCEMENT & FLOORING<br>DENT,SCRATCHES<br>الارضية        |
| 05.08 - Chassis (Frame)                  |        | REAR BOTH SIDE FRAME MEMBER END<br>REPAIRED,(STILL DENT)<br>الشاصية |
| 06 General Items                         |        | الاشياء العامة                                                      |
| 06.03 - Wiper Water System               |        | RESERVIOR CAP MISSING<br>نظام رش ماء ماسحات الزجاج                  |
| 06.14 - Transmission Condition           |        | OK<br>حالة ناقل الحركة                                              |
| 06.16 - Engine Condition, Smoke          |        | OIL LEAK<br>حالة المحرك - الدخان                                    |



### Test Certificate

|                     |                        |                    |                     |
|---------------------|------------------------|--------------------|---------------------|
| Site Number         | : 840-EMIRATES AUCTION | Plate Code         | : 0                 |
| Transaction Number  | : 19680580             | Plate Category     | : PRIVATE           |
| Transaction Date    | : 26 APR 2020 11:09:36 | Plate Number       | : 705975 EA         |
| Queue Number        | : 167764               | Import Doc. Ref.   | :                   |
| Chassis Number      | : JMYSRCS1AAU705975    | Manufacturer/Model | : MITSUBISHI/LANCER |
| Engine Number       | :                      | Model Year         | : 2010              |
| Vehicle Class       | : LIGHT VEHICLE        | Vehicle Color      | : SILVER            |
| Service / Indicator | : DSC AUCTION          |                    |                     |

### Statement of Vehicle Condition

|                                                                            |                        |                           |
|----------------------------------------------------------------------------|------------------------|---------------------------|
| 07 Remarks                                                                 |                        | ملاحظات                   |
| 07.04 - Others                                                             | 90385 KM               | ملاحظات اخرى              |
| 09 Auction                                                                 |                        | الفحص الكامل              |
| 09.02 - Need Wheel Alignment                                               |                        | بحاجة الى ميزانية العجلات |
| 09.14 - Sign Of Front Accident                                             |                        | أثر حادث في مقدمة المركبة |
| 09.15 - Sign Of Rear Accident                                              | BACK PANEL REPAIRED    | أثر حادث في مؤخرة المركبة |
| 09.25 - Body Repainted                                                     | BODY PORTION REPAINTED | أثر صبغ في المركبة        |
| The Test Certificate Shows the test Result at the time of inspection only. |                        |                           |

# Test Certificate

FAILED



|                             |                   |
|-----------------------------|-------------------|
| Possession Certificate :    | 63943058          |
| Chassis No :                | JMYSRCS1AAU705975 |
| Vehicle Make :              | MITSUBISHI        |
| Vehicle Model :             | LANCER            |
| Vehicle Class :             | Light Vehicle     |
| Body Type :                 | SALOON            |
| Fuel :                      | Benzene           |
| Color :                     | Silver            |
| Drive Direction :           | --                |
| Dimensions : (H x W x L)    | -- x -- x --      |
| Current Odometer :          | 90388 Kms.        |
| Previous Odometer Reading : | 159220 Kms.       |
| Origin :                    | Japan             |
| Gear Type :                 | --                |
| Engine No :                 | 4G13KD8451        |
| Axles No :                  | 2                 |
| No Of Doors :               | 4                 |
| G. V. W. :                  | 1500 Kgs.         |
| Model Year :                | 2010              |
| Engine Size :               | 1300 CC           |
| Horse Power :               | --                |
| Cylinders :                 | 4                 |
| No Of Seats :               | 5                 |
| Empty Weight :              | 1200 Kgs.         |

|                           |                          |
|---------------------------|--------------------------|
| Certificate Number :      | 5-TAS-2020-12102357      |
| Inspection Date :         | 05-07-2020               |
| Certificate Print Date :  | 05-07-2020               |
| Services :                | Registration Test        |
| Vehicle Testing Partner : | Tasjeel                  |
| Vehicle Testing Center :  | Tasjeel Emirates Auction |
| Total Time Taken :        | 12 min 38 sec            |
| Appointment Ref Number :  | --                       |
| Start Time :              | End Time :               |
| 15:42                     | 15:54                    |
| Lane :                    | Token No. :              |
| 01                        | 19                       |
| Attempt :                 | Prints No. :             |
| 1                         | 1                        |

## Parameter Readings

|                                              |                                             |                                                    |                                       |
|----------------------------------------------|---------------------------------------------|----------------------------------------------------|---------------------------------------|
| Service brake imbalance on front axle<br>7 % | Service brake imbalance on rear axle<br>5 % | Parking brake imbalance between LHS and RHS<br>3 % | Vehicle on Petrol CO Reading<br>0.4 % |
| Vehicle on Petrol HC Reading<br>233 PPM VOL  |                                             |                                                    |                                       |

## Inspection Findings

| Defects                                         | Issue              | Severity |
|-------------------------------------------------|--------------------|----------|
| Stop lamps<br>fix right side not working        | Bulb busted        | Major    |
| Rim<br>change rear right side rims dent         | Damaged, distorted | Major    |
| Tire<br>change rear both side cracks & old 2014 | Others (Major)     | Major    |
| Engine<br>repair oil leak                       | Others (Major)     | Major    |

| Discrepancies                           | Old Value  | New Value | Verified |
|-----------------------------------------|------------|-----------|----------|
| Odometer Device Odometer Reading Change | Authorized | Replaced  |          |

Inspection Remarks: rear both side frame member end & back panel repaired

Odometer Record  
Replace Events Date

05/07/2020