

Queue Number 2837370

Transaction Date 06 Oct 2026, 15:02:33

Site Name
840 - Emirates AuctionsTransaction Number
21058140 (CC10013) (CC10019)

Vehicle Details

Chassis Number	5N1CR2M82J*****
Specification	GCC Specification
Make	Nissan
Model	Pathfinder
Model Year	2018
Color	White
Mileage	234824 Km
Fuel Type	Hybrid
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION GETTING RUSTY	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR RUST PROOFED PORTION GETTING RUSTY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Trunk	REAR SWITCH DAMAGED	صندوق
01.H Fuel Tank	SIDE SAFETY BAR DENT / BEND	خزان الوقود

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS RUST PROOFED PORTION GETTING RUSTY / CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT COVER PORTION WORN OUT	حالة المقاعد
---------------------	------------------------------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR OIL LEAK , REFITTED , PARTS GETTING RUSTY , DELAY SHIFTING , MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Axle	OIL LEAK	اكسلات
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخرى
10.B Mirror	CENTER MIRROR PORTION LOOSE	المرآيا
10.C AC Condition	OK	المكيف
10.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.E Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	BOTTLE CAP DAMAGED / WATER LEVEL LOW	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on

لشكاوي والمقترحات يمكنك التواصل معنا عبر

