



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	24 May 2023, 10:39:26
Transaction Number	65483666 (CC10008)	Queue Number	725259



Chassis Number	2G1F91E3XD9179869
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Camaro
Model Year	2013
Color	Black
Mileage	205802 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED,PORTION STICKER	الصبغ
01.B Fenders	REFITTED	مدكار
01.C Vehicle Color	BLACK / BLUE	لون المركبة
01.D Bonnet	REFITTED	غطاء المحرك
01.E Floor	PORTION DENT	الارضية
02 Interior Condition		الحالة الداخليه
02.A Door Panel	FABRIC PORTION LOOSE	لوحة بطانة الباب
02.B AC Condition	OK	المكيف
02.C Roof Ceiling	PORTION LOOSE	بطانه السقف
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2021,CRACKED	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2021,CRACKED	الاطار الخلفي
03.C Rims Condition	MINOR DENT,SCRATCHES	حالة الجنوط
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
04.B Visual Gear Box Condition	REFITTED,JERKING	حالة الجير النظرى
05 Engine Condition		المحرك
05.A Other	UPPER COVER MIISSING	اخرى
05.B Visual Engine Condition	REFITTED	حالة المحرك النظرى
06 Exhaust System		نظام العادم
06.A Modification	MODIFIED ,NOISY	تعديلات
07 Chassis Condition		الشاسي
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.