



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 May 2022, 11:15:41
Transaction Number	25830592 (CC10008)	Queue Number	312309



Chassis Number	RKLBC42E7C4586373
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Corolla
Model Year	2012
Color	Red
Mileage	191311 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	OK	حالة الجير النظرى
02 Tires and Rims Condition		الاطارات
02.A Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
02.B Rims Condition	RIMS GETTING RUSTY	حالة الجنوط
02.C Front Tyre	BOTH SIDE 2018 & CRACKED	الاطار الامامي
03 Body		جسم المركبة
03.A Trunk	HAVE DENT	صندوق
03.B Fenders	FRONT RIGHT SIDE PORTION REPAIRED,REPAINTED & LEFT SIDE REPLACED	مدكار
03.C Paint	BODY PORTION REPAIRED, REPAINTED,MINOR DENT,SCRATCHES & PORTION FADED & PORTION RUSTY	الصبغ
03.D Bonnet	PORTION REPAIRED,REPAINTED & REFITTED	غطاء المحرك
03.E Doors	FRONT LEFT SIDE PORTION REPAINTED	أبواب
04 Suspension System		ممتص الصدمات

DEFECT	REMARKS	
04.A Shock Absorber	REAR BOTH SIDE SHOCK ABSORBER OIL LEAK	ممتص الصدمات
04.B Other	STABLIZER LINK BOOT CUT	اخرى
05 Steering Condition		المقود
05.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
05.B Axle	RIGHT SIDE INNER AXLE BOOT CUT	اكسلات
06 Seats Condition		المقاعد
06.A Seat Condition	SEATS HAVE EXTRA COVER	حالة المقاعد
07 Interior Condition		الحالة الداخلية
07.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
07.B AC Condition	OK & GRILL COVER MINOR CRACKED	المكيف
07.C Dash Board	PORTION DAMAGED	لوحة القيادة
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
08.B Fog light	NOT WORKING	كشاف الضباب
09 Engine Condition		المحرك
09.A Visual Engine Condition	SHAKING	حالة المحرك النظرى
09.B Mount	LOWER MOUNT RUBBER CRACKED	كرسي
10 Chassis Condition		الشاسي
10.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.