CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3001912
Transaction Date	17 Nov 2026, 14:18:58
Site Name	840 - Emirates Auctions
Transaction Number	38310685 (CC10021) (CC10021)



Vehicle Details

Chassis Number	MDHBN7AD7D*******
Specification	GCC Specification
Make	Nissan
Model	Sunny
Model Year	2013
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED PORTON RUSTY	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER BODY PARTS PORTION DENT,MUDDY	الارضية
01.D Bumper	MISALIGN,PORTION DAMAGED . SCRATCHES .	دعامية
01.E Sign of front accident	FRONT BUMPER FRAME , FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED,BEND	وجود مؤشر لحادث في المقدمة
01.F Sign of back accident	BACK PANEL , QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis Extension	REAR EXTENSION END DENT	تمديدات الشاسي
02.B Chassis	FRONT BOTH SIDE CHASSIS REPAIRED,BEND	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CRACK	ازرع
07.B Ball Joint	WORN OUT	مفصل كروي
07.C Stabilizer Bar And Link Rod	WORN OUT	عمود التوازن و مثبت عمود التوازن
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخري
08.B AC Condition	NOT CHECK	المكيف
08.C Power Window Switch And Glass	REAR LEFT SIDE QUARTER GLASS DAMAGED	مفتاح النافذه و الزجاج
08.D Door Panel	WORN OUT	لوحة بطانة الباب
08.E Steering Wheel and control buttons	ASSEMBLY COVER MISSING	عجلة القيادة وازرار التحكم
08.F Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae