



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>18 May 2023, 13:44:39</b>
Transaction Number	<b>35632823 (CC10013)</b>	Queue Number	<b>721328</b>



Chassis Number	<b>KMHTC61C4FU237734</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Hyundai</b>
Model	<b>Veloster</b>
Model Year	<b>2015</b>
Color	<b>Red</b>
Mileage	<b>294472 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	OK	المكيف
01.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Pillars	FRONT LEFT SID EA PILLAR DENT STRIP DAMAGED	القوائم
02.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
02.C Bonnet	SHOCK WEAK	غطاء المحرك
02.D Bumper	MISALIGN FADED	دعامية
02.E Floor	UNDER FLOOR PORTION COVERED MINOR DENT	الارضية
02.F Paint	BODY PORTION REPAINTED PORTION REPAIRED PORTION FADED MINOR DENT SCRATCHES	الصبغ
02.G Other	RIGHT SIDE RUNNING BOARD DENT	اخرى
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	OIL LEAK JERKING	حالة الجير النظري

DEFECT	REMARKS	
<b>04 Brake Condition</b>		<b>الفرامل</b>
04.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
<b>05 Chassis Condition</b>		<b>الشاسي</b>
05.A Chassis	CHASSIS COVERED CHECK VISIBLE AREA ONLY/OK	الشاسيه
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	LOWER ARM BUSH CRACK	ازرع
06.B Ball Joint	BOOT CUT	مفصل كروي
<b>07 Tires and Rims Condition</b>		<b>الاطارات</b>
07.A Front Tyre	BOTH SIDE 2019 CRACK DAMAGED	الاطار الامامي
07.B Rear Tyre	2018 2021 EXPIRED CRACKED DAMAGED	الاطار الخلفي
07.C Rims Condition	DENT SCRATCHES	حالة الجنوط
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
08.B Other	STABILIZER LINK BOOT CUT	اخرى
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Head Light	LENS FADED	الاضاءة الرئيسية
09.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
<b>10 Seats Condition</b>		<b>المقاعد</b>
10.A Seat Condition	PORTION CRACK	حالة المقاعد
<b>11 Engine Condition</b>		<b>المحرك</b>
11.A Visual Engine Condition	ABNORMAL NOISY OIL LEAK	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.