

Queue Number 2855842

Transaction Date 10 Oct 2026, 12:46:23

Site Name
840 - Emirates AuctionsTransaction Number
74816741 (CC10013) (CC10019)

Vehicle Details

Chassis Number	1N4AA6AP8G*****
Specification	Imported
Make	Nissan
Model	Maxima
Model Year	2016
Color	White
Mileage	172464 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED, PORTION REPAIRED ,PORTION STICKER,MINOR DENTS SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR SANDBLAST RUST PROOFED PORTION DENT	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Windshield	FRONT SPOT CRACKED	زجاج
01.G Bonnet	REFITTED	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD INNER FENDER FRAME SUPPORT REPAIRED , ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT LEFT SIDE CHASSIS END REPAIRED / BOTH SIDE SANDBLAST / PORTION DENT RUST PROOFED	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL PAN DENT , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	------------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT COVER PORTION DAMAGED	حالة المقاعد
---------------------	-----------------------------------	--------------

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Other	DENT	اخرى
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	OIL PAN DENT , PARTS GETTING RUSTY	الحالة النظرية للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
07.C Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
08 Lights		الاضاءة
08.A Head Light	BOTH SIDE BRACKET DAMAGED,LENS FADED	الاضاءة الرئيسية
08.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
09.B Other	SUSPENSION PARTS REFITTED	اخرى
10 Steering Condition		المقود
10.A Steering Oil	OIL LEAK	زيت المقود
11 Interior Condition		الحالة الداخلية
11.A Other	CENTER CONSOLE BOX COVER CRACKED , INTERIOR PARTS GETTING RUSTY	اخرى
11.B AC Condition	NOT COOLING	المكيف
11.C Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.D Air Bag	LEFT SIDE DAMAGED	وسائد هوائية
11.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	WATER LEVEL LOW	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae