

Queue Number 2649589

Transaction Date 17 Aug 2026, 13:24:10

Site Name
840 - Emirates AuctionsTransaction Number
33689950 (CC10021) (CC10011)

Vehicle Details

Chassis Number	5N1DR2MM5H*****
Specification	Imported
Make	Nissan
Model	Pathfinder
Model Year	2017
Color	White
Mileage	95055 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Bumper	MISALIGN,PORTION CRACK	دعامية

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,MUDDY,OILY,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED GETTING RUSTY, OIL LEAK,SHAKING	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	REFITTED GETTING RUSTY,MINOR OIL LEAK,MINOR JERKING	الحالة النظرية للجير
04.B Propeller Shaft	MISSING	ناقل الحركة
04.C DIFFERENTIAL	MISSING	الدفرنشيل
04.D Road Test	NOT CHECK	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2022 CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2022 CRACK	الاطار الخلفي

Condition	Remarks	الحالة
06 Lights الاضاءة		
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Suspension System ممتص الصدمات		
07.A Arms	BUSHES CRACK	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
07.C Stabilizer Bar And Link Rod	CRACK	عمود التوازن و مثبت عمود التوازن
08 Steering Condition المقود		
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
09 Interior Condition الحالة الداخلية		
09.A Other	INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخرى
09.B AC Condition	LOW COOLING,NOT WORKING PROPERLY	المكيف
09.C Audio	ATENNA DAMAGE	صوتيات
09.D Sun Visor	LEFT SIDE DAMAGED	حاجب الشمس
09.E Steering Wheel and control buttons	WORN OUT,HAVE PLAY	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
09.G Engine Start Button	GETTING WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae