





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 19898682	Plate Category	: PRIVATE
Transaction Date	: 04 JUN 2020 14:32:45	Plate Number	: 01875 EA
Queue Number	: 182998	Import Doc. Ref.	:
Chassis Number	: JTHBZ1BL2GA001875	Manufacturer/Model	: LEXUS/GS 350
Engine Number	:	Model Year	: 2016
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
01 Lights		الانوار
01.04 - Head Lights		الانوار الامامية
01.09 - Cover		غطاء انوار
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.04 - Rear Left And Right Hand Tires		الاطارات الخلفية
04.07 - Rims		الرنجات
05 Body		الهيكل
05.02 - Paint		الصبغ
05.03 - Doors		الابواب
05.04 - Fenders		المدكار
05.05 - Bumpers		الدعامية
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.06 - Chassis Ok	OK	الشاصي جيد
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.24 - Digital Display Damaged/Warning Lights		عطل في لوحة التحكم الالكتروني



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 19898682	Plate Category	: PRIVATE
Transaction Date	: 04 JUN 2020 14:32:45	Plate Number	: 01875 EA
Queue Number	: 182998	Import Doc. Ref.	:
Chassis Number	: JTHBZ1BL2GA001875	Manufacturer/Model	: LEXUS/GS 350
Engine Number	:	Model Year	: 2016
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

	MAINTENANCE REQUIRED	
09.25 - Body Repainted	BODY PORTION REPAINTED	أثر صنيغ في المركبة
09.26 - Accident Car	FRONT LEFT SIDE ACCIDENT	أثر حادث في المركبة
The Test Certificate Shows the test Result at the time of inspection only.		