

Queue Number 2762808

Transaction Date 17 Sep 2026, 16:47:43

Site Name
840 - Emirates AuctionsTransaction Number
16353635 (CC10009) (CC10011)

Vehicle Details

Chassis Number SCBET9ZA5G*****

Specification Imported

Make Bentley

Model Flying Spur

Model Year 2016

Color Blue

Mileage 49982 Km

Fuel Type Petrol

Transmission Type

No. Of Cylinders 8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED,REFITTED	مدمك
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,PAINT THICKNESS HIGH,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED,REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUTY	صدأ
01.E Floor	FLOOR COVERED, STEAM WASH REMOVE FRONT BOTH SIDE UNDER FENDER COVERS FOR RECHECK PROPERLY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Windshield	REAR CURTAIN NOT WORKING	زجاج
01.H Bonnet	STAY SHOCK NOT WORKING,REFITTED	غطاء المحرك
01.I Trunk	REFITTED,AUTO NOT WORKING PROPERLY,COMPARTMENT COVER MISSING,FIBER PAINT NOT CHECK	صندوق
01.J Door Handle &Lock	REAR RIGHT SIDE DOOR OUTER HANDLE NOT WORKING , FRONT LEFT SIDE AUTO CLOSE NOT WORKING	مقابض الأبواب والأقفال
01.K Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY MUDDY OILY CHECKED VISIBLE AREA ONLY/OK	الشاسية
02.B Chassis Number	STICKER PORTION FADED	رقم القاعدة

03 Engine Condition

المحرك

Condition	Remarks	الحالة
03.A Engine Visual Condition	OIL LEAK PARTS REFITTED, GETTING RUSTY	الحالة النظرية للمحرك
04 Exhaust System		نظام العادم
04.A Other	LEAK, HOLES REWELDED	اخرى
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING PARTS REFITTED GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 DRY CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING MESSAGE ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
09 Suspension System		ممتص الصدمات
09.A Other	SUSPENSION RUSTY, REFITTED	اخرى
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY ,INTERIOR REFITTED & CENTER CONSOLE BOX HAND RAST LOOSE/ ELECTRIC FAULT	اخرى
10.B Mirror	CENTER VIEW MIRROR LOOSE	المرآيا
10.C AC Condition	FRONT OK,REAR NOT WORKING	المكيف
10.D Roof Light	FRONT RIGHT SIDE NOT WORKING	أنارة السقف
10.E Power Window Switch And Glass	REAR BOTH SIDE NOT WORKING	مفتاح النافذه و الزجاج
10.F Dash Board	LEATHER REFITTED PORTION WORN OUT LOOSE CUT,GLOVE BOX LOOSE LOCK NOT WORKING	لوحة القيادة
10.G Engine Start Button	REMOTE WORN OUT,SWITCH PANEL LOOSE	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae