



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>09 Oct 2021, 18:03:59</b>
Transaction Number	<b>25100810 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>5TDBY64A2CS061794</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Sequoia</b>
Model Year	<b>2012</b>
Color	<b>Black</b>
Mileage	<b>250339 N/A</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Paint	BODY PORTION REPAIRED & REPAINTED, MINOR DENT , SCRATCHES	الصبغ
01.B Fenders	REAR LEFT SIDE REPAIRED, REPAINTED & FRONT RIGHT FENDER REPAINTED	مدكار
01.C Other	REAR LEFT ROOF RAIL REPAINTED	اخرى
01.D Bumper	REPAINTED & REAR LOWER PORTION MINOR DENT	دعامية
01.E Rusty	UNDER BODY PART , CHASSIS GETTING MINOR RUSTY	صدأ
01.F Roof	RIGHT ROOF INNER HANDLE BROKEN MISSING & ROOF CONSOLE COVER NOT CLOSING & ROOF CEILING LOSE	السقف
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Gear Box	REAR DIFFERENTIAL MINOR OIL LEAK	الجير
02.B Gear Box Mount	MOUNT BUSHES CRACKED	كرسي الجير
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Other	OIL LEAK	اخرى
<b>04 Chassis Condition</b>		<b>الشاسي</b>
04.A Chassis	OK	الشاسيه
<b>05 Seats Condition</b>		<b>المقاعد</b>
05.A Other	OK	اخرى
<b>06 Steering Condition</b>		<b>المقود</b>

DEFECT	REMARKS	
06.A Steering Oil	OIL LEAK	زيت المقود
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Arms	FRONT LOWER ARM & REAR CONTROL ARM BUSHES WORNOUT	ازرع
<b>08 Wipers and Arms</b>		<b>المساحات</b>
08.A Other	WORN OUT	اخرى
<b>09 Interior Condition</b>		<b>الاجزاء الداخلية</b>
09.A AC Condition	OK	المكيف
09.B Other	DASHBOARD CONSOLE BOX LOWER COVER LOSE&ROCKER PANEL COVER CRACKED FIXED BY BOLT	اخرى
<b>10 Lights</b>		<b>الاضاءة</b>
10.A Head Light	OK	الاضاءة الرئيسية
<b>11 Tires and Rims Condition</b>		<b>الاطارات</b>
11.A Front Tyre	BOTH 2020	الاطار الامامي
11.B Rear Tyre	BOTH 2020	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.