CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2946632
Transaction Date	06 Nov 2026, 09:38:35
Site Name	840 - Emirates Auctions
Transaction Number	98413862 (CC10008) (CC10011)



Vehicle Details

Chassis Number	5LMJJ3J51C*******
Specification	GCC Specification
Make	Lincoln
Model	Navigator
Model Year	2012
Color	White
Mileage	141162 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REPAINTED PORTION REPAIRED,RIGHT PORTION REPAINTED & REAR BOTH REPAIRED REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION GETTING RUSTY	الصبغ
01.C Doors	FRONT LEFT SIDE,REAR BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Bumper	MISALIGN,PORTION CRACK	دعامية
01.E Bonnet	FIBER PAINT NOT CHECK	غطاء المحرك
01.F Trunk	REPAIRED REPAINTED	صندوق
01.G Sign of side accident		وجود مؤشر لحادث في الجانب
01.H Sign of back accident		وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	COMPONENTS REFITTED	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION WORN OUT,MIDDLE LEFT SIDE FOLDING NOT WORKING PROPERLY	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OK	الحالة النظريه للجير
05.B Propeller Shaft	FRONT MISSING	ناقل الحركة
05.C Road Test	NOT CHECK	فحص علي الطريق
05.D Four Wheel Drive	DISCONNECTED	الدفع الرباعي
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.C Fog light	NOT WORKING	كشاف الضباب
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخري
09.B Mirror	LEFT SIDE LOOSE,BOTH SIDE AUTO FOLDING NOT WORKING	المرايا
09.C AC Condition	OK	المكيف
09.D Audio	FRONT LCD MODIFIED,REAR LEFT SIDE DAMAGED	صوتيات
09.E Sun Visor	RIGHT SIDE MIRROR COVER LOCK DAMAGED	حاجب الشمس
09.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN OUT LOOSE	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae