



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	15 Aug 2022, 12:30:19
Transaction Number	56246904 (CC10008)	Queue Number	312309



Chassis Number	KMHS81G5CU754998
Engine Number	
Vehicle Class	Car
Manufacturer	Hyundai
Model	Santa Fe
Model Year	2012
Color	Black
Mileage	144016 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Seats Condition		المقاعد
01.A Seat Belt	REAR BOTH SEAT BELT NOT WORKING	حزام الأمان
02 Interior Condition		الحالة الداخليه
02.A Other	REAR BOTH ROCKER PANEL COVER MISSING	اخرى
02.B AC Condition	OK	المكيف
02.C Power Window Switch	REAR RIGHT SIDE NOT WORKING	مفتاح النافذه
02.D Steering Wheel and control buttons	STEERING MINOR NOISY & WORN OUT	عجلة القيادة وازرار التحكم
03 Body		جسم المركبة
03.A Paint	BODY TOTALLY REPAINTED & PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
03.B Roof	ROOF RAIL,PORTION REPAIRED,REPAINTED	السقف
03.C Pillars	PILLAR OUTER PANEL PORTION REPAIRED,REPAINTED	القوائم
03.D Floor	UNDER FLOOR RUST PROOFED	الارضيه
04 Lights		الاضاءة
04.A Fog light	NOT WORKING	كشاف الضباب
04.B Brake Light	LEFT SIDE NOT WORKING	نور الفرامل

DEFECT	REMARKS	
05 Tires and Rims Condition		الاطارات
05.A Rear Tyre	LEFT SIDE 2018 CRACKED & RIGHT SIDE 2020	الاطار الخلفي
05.B Spare Tire &Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
05.C Front Tyre	BOTH SIDE 2018/2019 CRACKED & WORN OUT	الاطار الامامي
06 Engine Condition		المحرك
06.A Visual Engine Condition	MINOR OIL LEAK & REFITTED	حالة المحرك النظري
06.B Smoke	MINOR WHITE SMOKE	دخان
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CRACKED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Transmission Condition		الجير
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Visual Gear Box Condition	MINOR OIL LEAK & REFITTED	حالة الجير النظري
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10 Chassis Condition		الشاسي
10.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.