

Queue Number 2869088

Transaction Date 14 Oct 2026, 16:54:21

Site Name
840 - Emirates AuctionsTransaction Number
61318355 (CC10026) (CC10026)

Vehicle Details

Chassis Number	KNDPM3AC2K*****
Specification	Imported
Make	Kia
Model	Sportage
Model Year	2019
Color	Grey
Mileage	82437 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES , PORTION FADED	الصبغ
01.C Doors	REAR LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Floor	UNDER FLOOR PARTS THICK RUST PROOFED & THICK MUDDY	الارضية
01.E Bumper	MISALIGN , PORTION SCRATCHES	دعامية
01.F Bonnet	REPAINTED PORTION REPAIRED , REFITTED , MISALIGN	غطاء المحرك
01.G Pillars	LEFT SIDE C/PILLAR ROCKER PANEL REPAIRED	القوائم
01.H Trunk	NOT OPENING	صندوق
01.I Sign of back accident	BUMPER FRAME & LEFT SIDE WHEEL ARCH , RUNNING BOARD REPAIRED , DENT	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETE MUDDY , STEAM WASH FOR RECHECK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT STARTING , ALL SYSTEM NOT CHECK , MINOR OIL LEAK , THICK MUDDY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
---------------------	------------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECK , THICK MUDDY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 EXPIRED & LEFT SIDE DAMAGE	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2022 CRACK & RIGHT SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED , ALL LIGHT NOT CHECK	الاضاءة الرئيسية
08 Interior Condition		الحالة الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
08.B AC Condition	NOT CHECK , CONTROL SWICTH PORTION FADED	المكيف
08.C Sun Visor	RIGHT SIDE DAMAGE	حاجب الشمس
08.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae