

## **TEST CERTIFICATE**

مفصل كروي

Site Number
Transaction Number

04.A Ball Joint

840-Emirates Auctions 92549050 (CC10006) Transaction Date

25 Sep 2022, 10:23:35

Queue Number **595672** 

Chassis Number

SALVA2BGXGH107117

Engine Number

Vehicle Class Car

Manufacturer Range Rover

Model Evoque

Model Year 2016

Color Black

Mileage 66556 Km

Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification



## DEFECT REMARKS

O1 Interior Condition		الحاله الداخليه
01.A AC Condition	ОК	المكيف
01.B Sun Visor	LEFT SIDE MISALIGN	حاجب الشمس
O2 Body		جسم المركبة
02.A Fenders	REAR RIGHT SIDE QUARTER PANEL PORTION REPAINTED.FRONT BOTH SIDE REFITTED	مدكار
02.B Doors	FRONT RIGHT SIDE REPAINTED, PORTION REPAIRED.	أبواب
02.C Paint	BODY PORTION REPAIRED, REPAINTED . MINOR DENTS SCRATCHES ON BODY , FIBER BODY PARTS PAINT NOT CHECKED.	الصبغ
02.D Bonnet	REFITTED,SHOCK WEAK	غطاء المحرك
02.E Bumper	MISALIGN	دعامية
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2021.	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2021.	الاطار الخلفي
04 Suspension System		ممتص الصدمات

STABILIZER LINK ROD BUSHES, CUT.

DEFECT	REMARKS	
05 Transmission Condition		الجير
05.A Visual Gear Box Condition	OIL WET.JERKING.	حالة الجير النظرى
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Chassis Condition		الشاصي
06.A Chassis	CHECKED ONLY VISIBLE AREA OK.	الشاسيه
07 Engine Condition		المحرك
07.A Visual Engine Condition	OK	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.