





### Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	:
Transaction Number	: 27950909	Plate Category	:
Transaction Date	: 18 JUL 2021 10:00:54	Plate Number	:
Queue Number	: 373809	Import Doc. Ref.	: 017679 EA
Chassis Number	: JTGJX02P1A5017679	Manufacturer/Model	: TOYOTA/HI ACE
Engine Number	:	Model Year	: 2010
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION	Mileage	: 850493

#### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
01 Lights		الانوار
01.04 - Head Lights		الانوار الامامية
		B/S NOR WORKING & LHS LENS BROKEN.
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.11 - Shock Absorbers		مخمد الصدمات
		REAR WEAK LEAKS.
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
		REAR SUSPENSION LEAF SPRINGS BUSHES CRACKED.
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		ALL TYRES WORN OUT CRACKED WEAK 2018/2019.
04.08 - Spare Tires		الاطار الاحتياطي
05 Body		الهيكل
05.01 - Rusty		الصدأ
		UNDER FLOOR RUSTED HOLED AREAS.
05.02 - Paint		الصبغ
		BODY BUMPERS DENTS SCRATCHES & ROOF TOP RUSTY SPOTS.
05.03 - Doors		الابواب
		DOOR BIDINGS MISSING.
05.03 - Doors		الابواب
		RHS SLIDING DOOR OUTER HANDLE MISSING.
05.07 - Floor		الارضية
		B/S FLOOR RUNNING BOARDS REPAIRED.
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي
		FRONT REPLACED.
06 General Items		الاشياء العامة
06.08 - Interior Lights		الانوار الداخلية
		INTERIOR WEAR N TEAR & PANELS BROKEN.



### Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	:
Transaction Number	: 27950909	Plate Category	:
Transaction Date	: 18 JUL 2021 10:00:54	Plate Number	:
Queue Number	: 373809	Import Doc. Ref.	: 017679 EA
Chassis Number	: JTGJX02P1A5017679	Manufacturer/Model	: TOYOTA/HI ACE
Engine Number	:	Model Year	: 2010
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION	Mileage	: 850493

#### Statement of Vehicle Condition

06.12 - Seats Condition And Seats Fixing	DRIVER SEAT UNSECURE LOCK DIFFECTIVE.	المقاعد وحالتها وتثبيتها
06.12 - Seats Condition And Seats Fixing	INTERIOR FLOOR CARPET RORN OUT DAMAGED.	المقاعد وحالتها وتثبيتها
06.14 - Transmission Condition	OIL LEAKS.	حالة ناقل الحركة
06.16 - Engine Condition, Smoke	NEED TO TUNE UP ENGINE.	حالة المحرك - الدخان
06.21 - Battery Condition	DISCHARGED.	حالة البطارية
09 - Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.06 - Chassis Ok		الشاصي جيد
09.09 - Engine And Gear Box Performance Ok		فحص حالة الماكينة والجير
09.18 - A/C Not Cooling		عطل في المكيف
09.25 - Body Repainted		أثر صنيغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.		
شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسؤولة عن العيوب الخفية		