

Queue Number

2815262

Transaction Date

30 Sep 2026, 12:27:15

Site Name

840 - Emirates Auctions

Transaction Number

76557756 (CC10009) (CC10012)



Vehicle Details

Chassis Number

JHMEK3540W*****

Specification

GCC Specification

Make

Honda

Model

Civic

Model Year

1998

Color

Orange

Mileage

146521 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders

REFITTED

مدكار

01.B Paint

BODY TOTALY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION FADED , PORTION RUSTY

الصبغ

01.C Doors

ALL REFITTED , REAR RIGHT SIDE NOT OPEN

أبواب

01.D Rusty

UNDER BODY PARTS GETTING RUSTY

صدأ

01.E Floor

FLOOR PORTION FIRE WALL REPAIRED, REPAINTED PORTION DENT

الارضية

01.F Windshield

FRONT CRACKED

زجاج

01.G Bonnet

REFITTED

غطاء المحرك

01.H Trunk

REFITTED , MISALIGN

صندوق

01.I Sign of front accident

FRONT BUMPER FRAME BULK HEAD REPAIRED

وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis

REPAINTED , FRONT LEFT SIDE INNER REAR RIGHT SIDE EXTENSION MINOR DENT

الشاسيه

03 Engine Condition

المحرك

03.A Engine Visual Condition

MINOR OIL LEAK REFITTED GETTING RUSTY, AIR INTAKE PIPE MODIFIED

الحالة النظرية للمحرك

04 Exhaust System

نظام العادم

04.A Catalytic Converter

CUT REWELDED

دبة البيئة

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
07 Lights		الاضاءة
07.A Fog light	LEFT SIDE GRILL COVER MISSING	كشاف الضباب
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY	دواسة الفرامل
09 Steering Condition		المقود
09.A Steering Mount	WELDED REPAIRED	كرسي المقود
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY , INTERIOR REFITTED	اخرى
10.B AC Condition	OK	المكيف
10.C Power Window Switch And Glass	REAR RIGHT SIDE HANDLE LOOSE NOT WORKING , LEFT SIDE BOTH MISSING	مفتاح النافذه و الزجاج
10.D Door Panel	FRONT BOTH SIDE COVER MISSING	لوحة بطانة الباب
10.E Steering Wheel and control buttons	WORN OUT , HARD	عجلة القيادة وازرار التحكم
11 Battery Condition		حالة البطارية
11.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae