CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934212
Transaction Date	05 Nov 2026, 16:44:38
Site Name	840 - Emirates Auctions
Transaction Number	67658450 (CC10013) (CC10013)



Vehicle Details

Chassis Number	MA3ZC6B13F*******
Specification	GCC Specification
Make	Suzuki
Model	Swift
Model Year	2015
Color	Red
Mileage	286332 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.E Trunk	NOT CHECK	صندوق
01.F Fuel Tank	DENT	خزان الوقود
02 Chassis Condition		الشاصي
02.A Chassis	REAR RIGHT SIDE EXTENSION END DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED OIL LEAK . PARTS RUSTY , OIL PAN DENT	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER PORTION WORN OUT / REAR HEADREST MISSING	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	DENT	اخري
06 Transmission Condition		الجير

Condition	Remarks	الحالة
06.A Gear Box Visual Condition	MINOR JERKING REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	2024 DRY CRACK	الاطار الامامي
07.B Rear Tyre	2024 DRY CRACK	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Brake Pedal	SPONGY	دواسة الفرامل
09.B Disc&Drum	RUSTY	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	LEAK	ممتص الصدمات
10.B Arms	LOWER ARM BUSHES CUT	ازرع
10.C Ball Joint	BOOT CUT	مفصل كروي
10.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS RUSTY, SIGN OF FLOODED	اخري
11.B AC Condition	NOT WORKING	المكيف
11.C Roof Light	MISSING	أنارة السقف
11.D Dash Board	GETTING FADED PORTION WORN OUT CRACK	لوحة القياده
11.E Roof Ceiling	PORTION WORN OUT	بطانه السقف
11.F Sun Visor	LOOSE	حاجب الشمس
11.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae