





### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20132071	Plate Category	: PRIVATE
Transaction Date	: 04 JUL 2020 16:31:05	Plate Number	: 550749 EA
Queue Number	: 192390	Import Doc. Ref.	:
Chassis Number	: JN8FY15Y66X550749	Manufacturer/Model	: NISSAN/PATROL
Engine Number	:	Model Year	: 2006
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
01 Lights		الانوار
01.03 - Number Plate Lights		انوار لوحة الارقام
		NOT WORKING/WIPER/COOLANT RESERVOIR COVER MISSING
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		DOT 1818
05 Body		الهيكل
05.01 - Rusty		الصدأ
		CHASSIS & UNDER BODY COMPONENT RUSTY
05.02 - Paint		الصبغ
		DENT/SCRATCHES/FADED/PARTLY RUSTY
05.04 - Fenders		المدكار
		REAR BOTH FENDER REPAIRED
05.05 - Bumpers		الدعامية
		FRONT BUMPER/BULKHEAD/FENDER & FRAME REPAIRED
05.06 - Roof		السقف
		BONNET,BONNET HINGES/ROOF PANEL/ALL DOOR PILLAR REPAIRED/RUSTY
05.07 - Floor		الارضية
		MIDDLE FLOOR & FIREWALL REPAIRED
05.08 - Chassis (Frame)		الشاصية
		PARTLY DENT/BULGED/RUSTY
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي
		FRONT CRACKED/HEAD LIGHT LENS FADED
06 General Items		الاشياء العامة
06.01 - Wiper Blades		ماسحات الزجاج الامامي
		WIPER BLADE WORNOUT/SIDE MIRROR ADJUSTER & SUN ROOF NOT WORKING
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
		ACCELERATOR PEDAL PAD



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20132071	Plate Category	: PRIVATE
Transaction Date	: 04 JUL 2020 16:31:05	Plate Number	: 550749 EA
Queue Number	: 192390	Import Doc. Ref.	:
Chassis Number	: JN8FY15Y66X550749	Manufacturer/Model	: NISSAN/PATROL
Engine Number	:	Model Year	: 2006
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

06.13 - Exhaust System	MISSING/DASHBOARD MISSING COMPONENT/FADED MODIFIED	نظام العادم
07 Remarks		ملاحظات
07.04 - Others	288812 KM BONNET DAMPER WEAK	ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		يحتاج الى ميزانية العجلات
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.18 - A/C Not Cooling		عطل في المكيف
09.20 - Differential Not Ok	FRONT DIFFIRENTIAL GEAR & PROPELLER REMOVED/CANCELED	عطل في الدفرنش
09.25 - Body Repainted		أثر صيغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.		

# Test Certificate



FAILED

Change possession :	64167695	
Chassis No :	JN8FY15Y66X550749	
Vehicle Make :	NISSAN	
Vehicle Model :	PATROL	
Vehicle Class :	Light Vehicle	
Body Type :	STATION	
Fuel :	Benzene	
Color :	Gray	
Drive Direction :	--	
Dimensions :(H x W x L) -- x -- x --		
Current Odometer :	288814 Kms.	
Origin :	Japan	Model Year :
Gear Type :	--	2006
Engine No :	NIL	Engine Size :
Axles No :	2	3500 CC
No Of Doors :	4	Horse Power :
G. V. W. :	2600 Kgs.	--
	Cylinders :	
	6	
	No Of Seats :	
	5	
	Empty Weight :	
	1800 Kgs.	

Certificate Number :	5-TAS-2020-12112709	
Inspection Date :	07-07-2020	
Certificate Print Date :	07-07-2020	
Services :	Registration Test	
Vehicle Testing Partner :	Tasjeel	
Vehicle Testing Center :	Tasjeel Emirates Auction	
Total Time Taken :	14 min 32 sec	
Appointment Ref Number :	--	
Start Time :	10:12	End Time :
		10:27
Lane :	01	Token No. :
		3
Attempt :	1	Prints No. :
		1

## Parameter Readings

Service brake imbalance on front axle 3 %	Service brake imbalance on rear axle 5 %	Parking brake imbalance between LHS and RHS 0 %	Vehicle on Petrol CO Reading 0.15 %
Vehicle on Petrol HC Reading 57 PPM VOL			

## Inspection Findings

Defects	Issue	Severity
Pedal ACCELERATOR PEDAL FIX RUBBER	Others (Major)	Major
Front and Rear Windshields CHANGE FRONT CRACK	Front Cracked/broken (Major)	Major
Paint REPAIR PAINT FADED	Totally faded	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	4200	
Seats Incorrect Number of Seats	5	7	

## Inspection Remarks:

REAR BOTH SIDE CHASSIS BULGED/FRONT DIFFERENTIAL GEAR NOT AVAILABLE /UNDER BODY COMPONENTS RUSTY/BODY SCRATCH & DENT