



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	27 Nov 2022, 17:31:59
Transaction Number	55501693 (CC10010)	Queue Number	632254



Chassis Number	1FM5K8D85DGB45266
Engine Number	
Vehicle Class	Car
Manufacturer	Ford
Model	Explorer
Model Year	2013
Color	Silver
Mileage	242833 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Mirror	RIGHT SIDE ASSEMBLY COVER DAMAGED	المرآيا
01.B AC Condition	NOT WORKING	المكيف
02 Brake Condition		الفرامل
02.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
03 Body		جسم المركبة
03.A Floor	LEFT SIDE OUTER PANEL COVER MISSING,UNDER FLOOR PORTION DENT	الارضية
03.B Paint	BODY PORTION REPAIRED ,REPAINTED ,DENTS SCRATCHES PORTION FADED.	الصبغ
03.C Doors	FRONT RIGHT SIDE DENT	أبواب
03.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
03.E Bumper	MISALIGN,PORTION DAMAGED.	دعامية
03.F Fenders	FRONT BOTH SIDE MISALIGN,PORTION DAMAGED	مذكار
04 Engine Condition		المحرك
04.A Visual Engine Condition	ABNORMAL NOISY	حالة المحرك النظري
05 Suspension System		ممتص الصدمات

DEFECT	REMARKS	
05.A Shock Absorber	LEAK	ممتص الصدمات
05.B Arms	LOWER ARM BUSH CRACKED	ازرع
06 Seats Condition		المقاعد
06.A Seat Condition	COVER PORTION DAMAGED	حالة المقاعد
07 Tires and Rims Condition		الاطارات
07.A Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
07.B Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي
08 Lights		الاضاءة
08.A Head Light	LENS FADED.	الاضاءة الرئيسية
08.B Fog light	LEFT SIDE MISSING.	كشاف الضباب
09 Transmission Condition		الجير
09.A Visual Gear Box Condition	OK	حالة الجير النظري
09.B Road Test	NOT CHECK	فحص علي الطريق
10 Chassis Condition		الشاسي
10.A Chassis	VISIBLE AREA OK.	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.