



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	19 Jan 2023, 17:01:11
Transaction Number	22611662 (CC10009)	Queue Number	659845



Chassis Number	WPOZZZ97ZBL000080
Engine Number	
Vehicle Class	Car
Manufacturer	Porsche
Model	Panamera
Model Year	2011
Color	White
Mileage	173251 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Head Light	RIGHT SIDE CRACKED	الاضاءة الرئيسية
01.B Tail Light	REAR BOTH SIDE DAMAGED	الانارة
01.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
02 Body		جسم المركبة
02.A Paint	BODY TOTALLY REPAINTED , PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
02.B Sign of front accident		وجود مؤشر لحادث في المقدمة
02.C Floor	UNDER FLOOR FEDNER CHASSIS COVERED CHCKED VISIBLE AREA ONLY	الارضية
02.D Bonnet	SHOCK WEAK REFITTED	غطاء المحرك
02.E Sign of side accident		وجود مؤشر لحادث في الجانب
03 Engine Condition		المحرك
03.A Visual Engine Condition	OIL LEAK REFITTED	حالة المحرك النظري
03.B Mount	MOUNT RUBBER CRACKED	كرسي
03.C Smoke	BLACK SMOKE	دخان
04 Transmission Condition		الجير

DEFECT	REMARKS	
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Visual Gear Box Condition	MINOR OIL LEAK REFITTED/ JERKING	حالة الجير النظري
04.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
05 Chassis Condition		الشاسي
05.A Chassis	FRONT RIGHT SIDE CHASSIS UPPER EDGE BEND	الشاسيه
06 Suspension System		ممتص الصدمات
06.A Arms	LOWER ARM BUSHES CUT	ازرع
06.B Ball Joint	BOOT CUT	مفصل كروي
07 Interior Condition		الحاله الداخليه
07.A AC Condition	OK	المكيف
07.B Sunroof	CURTAIN DAMAGED	فتحت سقف
07.C Roof Ceiling	LOOSE	بطانه السقف
07.D Power Window Switch	REAR CURTAIN DAMAGED	مفتاح النافذه
07.E Dash Board	PORTION LOOSE	لوحة القيادة
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادت

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Transfer Certificate :	62312558
Chassis No :	WPOZZZ97ZBL000080
Vehicle Make :	PORSCHE
Vehicle Model :	PANAMERA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	173254 Kms. x
Origin : Germany	Model Year : 2011
Gear Type : Automatic	Engine Size : 3600 CC
Engine No : M4620B00512	Horse : --
Axles No : 2	Power :
No Of : 4	Cylinders : 6
Doors :	No Of Seats : 4
G. V. W. : 1500 Kgs.	Empty : 1000 Kgs.
	Weight :

Certificate Number :	5-TAS-2023-18606611		
Inspection Date :	21-01-2023		
Certificate Print Date :	21-01-2023		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Qusais		
Total Time Taken :	7 min 38 sec		
Appointment Ref Number :	--		
Start Time :	11:57	End Time :	12:05
Lane :	02	Token No. :	246
Attempt :	2	Prints No. :	1

Carbon footprint



Take action to protect Dubai environment

Estimated Vehicle Consumption (Rate last 12 Months)

35845 KM	3689 L	12801 AED	8.9 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Inspection Remarks:

OLD ODO METER 18/03/2018/ 263016 KM ROLL BACK 173254 KM/ FRONT BUMPER/ BULKHEAD/REPAIRED/ FLOOR PARTLY DENT& REAR LENS CRACK CHANGE AS SSON AS POSSIBLE



Odometer Record
Replace Events Date

20/01/2023

Payment Details

Inspection Performed by 35344 17588 17588	Payment Method Cash	Transaction Number 18606611	Service Fees AED 70 Collected on 21/01/2023
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Badiya Ali Ahmed Al Bulushi

- This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

