

Queue Number	2891474	Transaction Date	21 Oct 2026, 13:07:40
Site Name	840 - Emirates Auctions	Transaction Number	21159327 (CC10026) (CC10026)
		Vehicle Details Chassis Number JTEJU9FJXB***** Specification GCC Specification Make Toyota Model Land Cruiser Model Year 2011 Color Black Mileage 420401 Km Fuel Type Petrol Transmission Type No. Of Cylinders 6	

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED , REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION RUSTY	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.F Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.G Sign of front accident	BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
01.H Vehicle Color	WHITE	لون المركبة
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS FRAME GETTING RUSTY , THICK RUST PROVED , RIGHT SIDE MIDDLE CHASSIS RUSTY HOLE WEAK , DENT	الشاسيه
02.B Chassis Number	VIN # GETTING RUSTY	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,PARTS REFITTED SIGN OF OIL WET . PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED PARTS , REFITTED SIGN OF OIL WET PARTS GETTING RUSTY	الحالة النظرية للجير

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY , NOT WORKING	دواسة الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحالة الداخلية
09.A Other	CENTER CONSOLE BOX PORTION WORN OUT , INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخرى
09.B AC Condition	NOT CHECK	المكيف
09.C Dash Board	PORTION WORN OUT	لوحة القيادة
09.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
09.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوى والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae