CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899744
Transaction Date	29 Oct 2026, 13:24:34
Site Name	840 - Emirates Auctions
Transaction Number	53631498 (CC10010) (CC10011)



Vehicle Details

Chassis Number	2T1BURHE7F*******
Specification	Imported
Make	Toyota
Model	Corolla
Model Year	2015
Color	White
Mileage	340276 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION GETTING RUSTY	الصبغ
01.C Doors	FRONT RIGHT SIDE REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	FLOOR PORTION DENT ,BOTH SIDE RUNNING BOARD REPAIRED DENT LOOSE	الارضية
01.F Bumper	MISALIGN,SCRATCHES	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA END PORTION MINOR DENT.	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL LEAK COMPONENT PARTS RUSTY SHAKING ,ABNORMAL NOISY .	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	EXTRA COVER PORTION CUT	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL LEAK ,JERKING , COMPONENT PARTS RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED . .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACKED PUNCTURE.,	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY,	دواسة الفرامل
08.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CRACKED.	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CRACKED.	ربلة المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B AC Condition	NO COOLING	المكيف
11.C Door Panel	PORTION WORN OUT .	لوحة بطانة الباب
11.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.E Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.