



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	17 Oct 2021, 17:57:44
Transaction Number	49169621 (CC10006)	Queue Number	312309



Chassis Number	JTGHJ01JX53007201
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Land Cruiser
Model Year	2005
Color	White
Mileage	0 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY REPAIRED EXCEPT BONNET REPAINT & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	REPAIRED, REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS, FLOORING , SUSPENTION , CHASSIS GETTING RUSTY	صدأ
01.E Floor	FRONT FLOORING OPEN & REAR QUATER PANEL, WHEEL HOSUING, RUNNING BOARD REPAIRED	الارضية
01.F Bumper	FRONT FENDER FRAME, BUMPER FRAME , RADITOR SUPPORT , BULK HEAD & CROSSMEMBER REPAIRED	دعامية
01.G Roof	REPAIRED & REPAINTED (FOR REGISTRATION NEED TO REMOVE ALL PILLAR COVER FOR RECHECK)	السقف
01.H Bonnet	REPAINTED & SHOCK WEAK	غطاء المحرك
01.I Pillars	ALL REPAIRED (FOR REGISTRATION NEED TO REMOVE ALL PILLAR COVER FOR RECHECK)	القوائم
01.J Trunk	REPAIRED & INNER COVER MISSING	صندوق
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS FRAME COMPLETLY RUST PROOFED & RUSTY (FOR REGISTRATION NEED TO REMOVE ALL RUST	الشاسيه

DEFECT	REMARKS	
PROOFED& CLEAN FOR RECHECK)		
03 Engine Condition		المحرك
03.A Engine Condition	OIL LEAK & REFFITED	حالة المحرك
04 Seats Condition		المقاعد
04.A Seat Condition	REAR MISSING	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	WELDED & REPAIRED	اخرى
06 Transmission Condition		الجير
06.A Gear Box	OIL LEAK & REFFITED	الجير
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	NOT WORKING PROPERLY & REAR MISSING	ازرع المساحات والشفرات
08 Lights		الاضاءة
08.A Head Light	RIGHT SIDE HIGH BEAM NOT WORKING	الاضاءة الرئيسية
08.B Other	OK	اخرى
09 Brake Condition		الفرامل
09.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Suspension Subframe	SUSPENTION SUB FRAME GETTING RUSTY	
10.B Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED, RUSTY	ازرع
11 Steering Condition		المقود
11.A Steering Boot	BOOT LEAKING	ربلة المقود
11.B Tie Rod End	BOOT CUT	مؤخرة الروداد
11.C Other	STABILIZER LINK & CONTROL BAR BUSHES DRY CRACKED	اخرى
11.D Axle	BOOT LEAKING	اكسلات
11.E Steering Box	OIL LEAK	جهاز المقود
12 Interior Condition		الحالة الداخليه
12.A Mirror	NOT WORKING PROPERLY	المرايا
12.B AC Condition	NOT WORKING	المكيف
12.C Roof Ceiling	COVER DAMAGED & LOSE	بطانه السقف
12.D Floor Matting	COVER DAMAGED	فرش الأرضيه
12.E Odometer reading	83355 KM	قراءة عداد المسافات
13 Tires and Rims Condition		الاطارات
13.A Other	FRONT BOTH SIDE TIRES OUT OF ALIGNMENT & BODY LEVEL LOW	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.