



Test Certificate

Site Number	: 756-TASJEEL SHARJAH	Plate Code	:
Transaction Number	: 17529877	Plate Category	:
Transaction Date	: 10 JUN 2019 16:40:59	Plate Number	:
Queue Number	: 81416	Import Doc. Ref.	: 98780 DXB
Chassis Number	: 2C3CDXHGOFH798780	Manufacturer/Model	: DODGE/CHARGER
Engine Number	:	Model Year	: 2015
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: RED
Service / Indicator	: DSC AUCTION	Mileage	: 53939

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Failed	فحص مخمد الصدمات
VISUAL TEST:		
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
	FRT B/S TIRE CRACKED, WORN OUT	
04.04 - Rear Left And Right Hand Tires		الاطارات الخلفية
	RR LHS TIRE CRACKED	
05 Body		الهيكل
05.02 - Paint		الصبغ
	BODY SPOT DENT, SCRATCH	
09 Auction		الفحص الكامل
09.06 - Chassis Ok	OK	الشاصي جيد
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
	BONNET DENT, BULK HEAD DAMAGED	
The Test Certificate Shows the test Result at the time of inspection only.		
شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط		