CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899687
Transaction Date	28 Oct 2026, 15:00:09
Site Name	840 - Emirates Auctions
Transaction Number	24934103 (CC10026) (CC10021)



Vehicle Details

Chassis Number	3KPF54ADXK*******
Specification	Imported
Make	Kia
Model	Forte
Model Year	2019
Color	Orange
Mileage	72998 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED , REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.E Bumper	MISALIGN , PORTION FADED	دعامية
01.F Bonnet	PORTION REPAIRED , REFITTED	غطاء المحرك
01.G Pillars	FRONT LEFT SIDE A PILLAR OUTER POST REPAIRED	القوائم
02 Chassis Condition		الشاصي
02.A Chassis	FRONT LEFT CHASSIS OUTER SKIRT BRACKET REPAIRED	الشاسيه
02.B Other	NEED TO REMOVE FRONT FENDER INNER COVER FOR PROPER INSPECTION	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED PARTS GETTING RUSTY , OIL LEAK	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات

CAR CHECK

Condition	Remarks	الحالة
05.A Front Tyre	LEFT SIDE 2024 WORN OUT & RIGHT SIDE 2023	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06 Lights		الاضاءة
06.A Tail Light	RIGHT SIDE CRACK	الضوء الخلفي
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACK	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
07.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
08 Interior Condition		الحاله الداخليه
08.A Other	CENTER CONSOLE BOX COVER PORTION WORN OUT	اخري
08.B AC Condition	OK	المكيف
08.C Dash Board	PORTION WORN OUT	لوحة القياده
08.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
08.F Gear Shifting Lever	PORTION WORN OUT , SHIFTER LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae