



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	23 Dec 2021, 18:13:33
Transaction Number	60584373 (CC10006)	Queue Number	312309



Chassis Number	WBAJA5103JB124374
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	530I
Model Year	2018
Color	White
Mileage	184966 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Seats Condition		المقاعد
01.A Seat Belt	OK	حزام الأمان
01.B Seat Condition	OK	حالة المقاعد
02 Wipers and Arms		المساحات
02.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات
03 Interior Condition		الحالة الداخليه
03.A AC Condition	OK	المكيف
03.B Dash Board	DASHBOARD LEATHER REPLACED	لوحة القيادة
04 Body		جسم المركبة
04.A Fenders	FRONT RIGHT SIDE REPAINTED,BOTH SIDE REFITIED	مدكار
04.B Bonnet	PORTION REPAIRED , REPAINTED , REFITTED,MISALIGN	غطاء المحرك
04.C Paint	BODY PORTION REPAINTED,PORTION REPAIRED,BODY MINOR DENT,SCRATCHES	الصبغ
04.D Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخرى
04.E Bumper	REPAINTED	دعامية
04.F Sign of front accident		وجود مؤشر لحادث في المقدمة

DEFECT	REMARKS	
04.G Floor	UNDER FLOOR FULLY COVERED	الارضية
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
05.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
06 Chassis Condition		الشاصي
06.A Chassis	NEED TO REMOVE FENDER COVER&UNDER ENGINE COVER ,UNDER FLOOR COVER ,SHIELD COVER FOR CHECK	الشاسيه
06.B Chassis Number	CHASSIS NUMBER AREA REPAIRED NEED TO REMOVE PAST ,PAINT &UPPER COVER FOR CHECK	رقم القاعدة
07 Engine Condition		المحرك
07.A Engine Condition	OK	حالة المحرك
08 Transmission Condition		الجير
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Gear Box	OK	الجير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	WBAJA5103JB234374
Vehicle Make :	BMW
Vehicle Model :	530
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	185008 Kms.
Origin :	Germany
Model Year :	2018
Gear Type :	Automatic
Engine Size :	2000 CC
Engine No :	16875242
Horse Power :	191
Axles No :	2
Cylinders :	6
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 1593 Kgs.
	2000 Kgs.

Certificate Number :	5-TAS-2022-15832177
Inspection Date :	06-01-2022
Certificate Print Date :	06-01-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Qusais
Total Time Taken :	11 min 23 sec
Appointment Ref Number :	--
Start Time :	11:15
End Time :	11:26
Lane :	03
Token No. :	190
Attempt :	1
Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

492 KM	35 L	57 AED	0.1 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
10 %	25 %	7 %	0 %
Vehicle on Petrol HC Reading			
3 PPM VOL			

Inspection Remarks:

FRONT RIGHT SIDE CHASSIS REPAIRED,BULK HEAD,FENDER FRAME,VIN FRAME REPAIRED,C.C.M REPORT-2022-01-05-3//

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
35020 63469 63469	Cash	15832177	AED 170 Collected on 06/01/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Maimouna Ali Abdulla Albalushi

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل للمركبة. لا يمتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أفراس البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.