

Queue Number 2869091

Transaction Date 16 Oct 2026, 12:27:24

Site Name
840 - Emirates AuctionsTransaction Number
89580594 (CC10010) (CC10010)

Vehicle Details

Chassis Number	1N4BL4CV7K*****
Specification	Imported
Make	Nissan
Model	Altima
Model Year	2019
Color	White
Mileage	89986 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED REPAINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED ,DENTS SCRATCHES ,	الصبغ
01.C Doors	LEFT SIDE BOTH DOORS REPAINTED PORTION REPAIRED.	أبواب
01.D Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	MISALIGN ,SCRATCHES .	دعامية
01.G Bonnet	REFITTED REPAINTED PORTION REPAIRED.	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ,FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS END DENT , APRON JOINT AREA SLIGHTLY DETACHED , CHASSIS COMPLETE COVERED ,CHECKED ONLY VISIBLE AREA .	الشاسيه
02.B Other	NEED TO REMOVE FENDER ,UNDER COVER FOR INSPECTION .	اخرى

03 Engine Condition

المحرك

03.A Mount	TOP MOUNT CUT .	كرسي
03.B Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED PARTS RUSTY ,UNDER PORTION COVERED.	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	PORTION CUT .	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED PARTS RUSTY ,UNDER PORTION COVERED.	الحالة النظره للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES .	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Other	TANK CAP MISSING	اخرى
08 Lights		الاضاءة
08.A Head Light	LENS GETTING FADED ,ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Disc&Drum	PARTS RUSTY.	دسك و طنايير الفرامل
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	MINOR LEAK .	ممتص الصدمات
10.B Arms	BUSHES CRCKED.	ازرع
11 Steering Condition		المقود
11.A Tie Rod End	BALL JOINT BOOT CUT.	مؤخرة الرودادات
12 Interior Condition		الحاله الداخليه
12.A Other	INTERIOR PARTS GETTING RUSTY.	اخرى
12.B AC Condition	NOT CHECKED.	المكيف
12.C Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
12.D Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae