CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2997335
Transaction Date	16 Nov 2026, 16:52:20
Site Name	840 - Emirates Auctions
Transaction Number	31678186 (CC10013) (CC10011)



Vehicle Details

Chassis Number	JTEBU25J69*******
Specification	GCC Specification
Make	Toyota
Model	Prado
Model Year	2009
Color	White
Mileage	545900 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAIRED REPAINTED,MINOR DENT SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK	الارضية
01.E Bumper	MINOR SCRATCHES	دعامية
01.F Roof	ROOF,ROOF RAIL REPAIRED	السقف
01.G Bonnet	REFITTED	غطاء المحرك
01.H Pillars	LEFT SIDE A/B/PILLAR REPAIRED	القوائم
01.I Vehicle Model	LAND CRUISER PRADO	طراز المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME GETTING RUSTY PORTION BULGED RUSTY HOLE	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OPEN REFITTED , PARTS GETTING RUSTY , ABNORMAL NOISY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER,DRIVER SEAT PORTION CUT & REAR RIGHT SIDE STUCK FOLDING NOT WORKING PROPERLY	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Four Wheel Drive	LEVER STUCK (NOT ENGAGED)	الدفع الرباعي
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACK	الاطار الخلفي
06.C Rims Condition	HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Tail Light	LEFT SIDE SIGN OF CRACK	الضوء الخلفي
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Steering Oil	MINOR OIL LEAK	زيت المقود
09.B Steering Boot	BOOT CUT	ربلة المقود
09.C Tie Rod End	BOOT CUT	مؤخرة الرودات
09.D Axle	BOOT CUT	اكسلات
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
10.B Mirror	RIGHT SIDE AUTO FOLDING NOT WORKING,BRACKET DAMAGED REPAIRED	المرايا
10.C AC Condition	OK,FRONT GRILL PORTION DAMAGED	المكيف
10.D Roof Light	SUNGLASS BOX LOCK DAMAGED	أنارة السقف
10.E Dash Board	PORTION CRACKED WORN OUT	لوحة القياده
10.F Sunroof	NOT WORKING	فتحت سقف
10.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae