

Queue Number

2852259

Transaction Date

09 Oct 2026, 16:37:39

Site Name

840 - Emirates Auctions

Transaction Number

47807835 (CC10026) (CC10026)



Vehicle Details

Chassis Number	JHMF16216*****
Specification	GCC Specification
Make	Honda
Model	Civic
Model Year	2006
Color	White
Mileage	365114 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES , GETTING RUSTY	الصبغ
01.C Doors	REAR BOTH SIDE REFITTED	أبواب
01.D Floor	UNDER FLOOR THICK RUST PROOFED , MINOR DENT	الارضية
01.E Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.F Bonnet	LEVER PANEL FOR OPENING DAMAGE ,	غطاء المحرك
01.G Trunk	REFITTED , MISALIGN	صندوق
01.H Sign of front accident	BUMPER FRAME , INNER FENDER FRAME , RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL , BUMPER FRAME , WHEEL ARCH REPAIRED , DENT	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS GETTING RUSTY , OILY	الشاسيه
--------------	------------------------------	---------

03 Engine Condition

المحرك

03.A Other	OIL PAN DAMAGE FIXS BY SELICON	اخرى
03.B Engine Visual Condition	ENGINE NOT STARTING , ALL SYSTEM NOT CHECK , PARTS REFITTED GETTING RUSTY SIGN OF OIL WET	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION CRACK , FRONT BOTH SIDE SEAT HAVE PLAY	حالة المقاعد
---------------------	--	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	ALL SYSTEM NOT CHECK , PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED , ENGINE NOT STARTING , ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07.B Indicator & Hazard light	HAZARD BUTTON FADED	الاشارات
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10 Interior Condition		الحالة الداخليه
10.A Other	CENTER CONSOLE BOX LOCK DAMAGE , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
10.B Mirror	BOTH SIDE VIEW MIRROR HOUSING LOOSE	المرايا
10.C AC Condition	NOT CHECK , VENT ADJUSTABLE DAMAGE	المكيف
10.D Floor Matting	DIRTY	فرش الأرضيه
10.E Dash Board	PORTION DAMAGE	لوحة القيادة
10.F Roof Ceiling	FABRIC LOOSE	بطانه السقف
10.G Sun Visor	LEFT SIDE LOOSE	حاجب الشمس
10.H Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.J Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
10.K Engine Start Button	REMOTE PORTION WORN OUT	زر تشغيل المحرك
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae