



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	20 Jul 2022, 18:04:05
Transaction Number	27763912 (CC10006)	Queue Number	312309



Chassis Number	5TFEY5F16LX269885
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Tundra
Model Year	2020
Color	Beige
Mileage	84536 Miles
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY TOTALY REPAINTED & PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.B Sign of side accident		وجود مؤشر لحادث في الجانب
01.C Other	FRONT FENDER FRAME, BUMPER FRAME, RADITOR SUPPORT ,RIGHT SIDE WHEEL ARCH REPAIRED	اخرى
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	OIL LEAK & REFITTED	حالة الجير النظري
03 Interior Condition		الحاله الداخليه
03.A AC Condition	OK	المكيف
03.B Air Bag	DAMAGED	وسائد هوائية
03.C Roof Ceiling	PORTION LOOSE	بطانه السقف
03.D Steering Wheel and control buttons	HORN NOT WORKING	عجلة القيادة وازرار التحكم
04 Lights		الاضاءة
04.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير

DEFECT	REMARKS	
04.B Fog light	BOTH SIDE COVER LOOSE	كشاف الضباب
05 Engine Condition		المحرك
05.A Visual Engine Condition	OIL LEAK DRIPPING,REFITTED	حالة المحرك النظري
06 Suspension System		ممتص الصدمات
06.A Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
06.B Arms	LOWER ARM BUSHES CRACKED	ازرع
07 Chassis Condition		الشاصي
07.A Other	CHASSIS FRAME COMPLETELY PAINTED (FOR RECHECK PROPERLY NEED TO REMOVE PANT)	اخرى
07.B Chassis	FRONT RIGHT SIDE CHASSIS ALIGN REPAIRED, GETTING RUSTY	الشاسيه
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Change possession :	66683492
Chassis No :	5TFEY5F16LX269885
Vehicle Make :	TOYOTA
Vehicle Model :	TUNDRA
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	Piege
Drive Direction :	Left Hand Side
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	136047 Kms.
Origin : United States	Model Year : 2020
Gear Type : Automatic	Engine Size : 5700 CC
Engine No : NIL	Horse 381
Axles No : 2	Power :
No Of 4	Cylinders : 8
Doors :	No Of Seats : 5
G. V. W. : 3200 Kgs.	Empty 2200 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17344747
Inspection Date :	04-08-2022
Certificate Print Date :	04-08-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Warsan
Total Time Taken :	9 min 12 sec
Appointment Ref Number :	--
Start Time : 17:30	End Time : 17:39
Lane : 01	Token No. : 269
Attempt : 1	Prints No : 1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
8 %	23 %	21 %	0.19 %

Vehicle on Petrol HC Reading
60 PPM VOL

Inspection Findings

Defects	Issue	Severity
Engine	Oil leaking continuously	Major

Inspection Remarks:

FRONT BOTH SIDE FENDER FRAME,RADIATOR FRAME,BULKHEAD REPAIRED & COMPLETE CHASSIS SANDBLASTED.(old)

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
33409	VTP Credit Account	17344747	AED 170 Collected on 04/08/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Shoib Ali

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

