



Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	:
Transaction Number	: 19557005	Plate Category	:
Transaction Date	: 01 APR 2020 13:47:46	Plate Number	:
Queue Number	: 166651	Import Doc. Ref.	: 76712 EA
Chassis Number	: KMHDG41E3DU676712	Manufacturer/Model	: HYUNDAI/ELANTRA
Engine Number	:	Model Year	: 2013
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION	Mileage	: 279362

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Failed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
05 Body		الهيكل
05.02 - Paint		الصيغ
		BODY PORTION DENT & SCRATCHES ,FADED
05.04 - Fenders		المدكار
		FRT LHS FENDER REPD
05.05 - Bumpers		الدعامية
		B/S BUMPER & B/FRAME REPD
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		279362 KM
09 Auction		الفحص الكامل
09.06 - Chassis Ok	OK	الشاصي جيد
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.25 - Body Repainted		أثر صيغ في المركبة
		FRT LHS FENDER,ROOF,RR LHS Q/PANEL

The Test Certificate Shows the test Result at the time of inspection only.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط