

Queue Number

2698881

Transaction Date

31 Aug 2026, 16:42:10

Site Name

840 - Emirates Auctions

Transaction Number

82169687 (CC10009) (CC10012)



Vehicle Details

Chassis Number	WPOZZZ97ZB*****
Specification	GCC Specification
Make	Porsche
Model	Panamera
Model Year	2011
Color	White
Mileage	80771 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED & REAR LEFT SIDE PORTION REPAINTED , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH PORTION REPAINTED , RIGHT SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COMPLETELY COVERED, CHECKED VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN , PORTION DAMAGED	دعامية
01.G Roof	PORTION REPAINTED	السقف
01.H Bonnet	REPAINTED PORTION REPAIRED , REFITTED	غطاء المحرك
01.I Sign of front accident	FRONT BUMPER FRAME BULK HEAD ASSEMBLY REFITTED, RIGHT SIDE RADIATOR SUPPORT CRACKED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK PARTS REFITTED,OVERHEAT	الحالة النظرية للمحرك
------------------------------	----------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION CRACK , DRIVER SEAT SIDE COVER PORTION LOOSE	حالة المقاعد
---------------------	--	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL WET,MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	FRONT PORTION DAMAGED	ازرع المساحات والشفرات
08 Lights		الاضاءة
08.A Head Light	LENS FADED , LEFT SIDE CRACK , RIGHT SIDE PORTION LOOSE	الاضاءة الرئيسية
08.B Tail Light	FADED , RIGHT SIDE DAMAGED	الضوء الخلفي
09 Suspension System		ممتص الصدمات
09.A Other	SUSPENSION REFITTED	اخرى
09.B Ball Joint	BOOT CUT	مفصل كروي
09.C Hydraulic System	NOT WORKING	النظام الهيدروليكي
10 Interior Condition		الحالة الداخلية
10.A AC Condition	OK,SWITCH NOT WORKING PROPERLY	المكيف
10.B Power Window Switch And Glass	REAR LEFT SIDE SWIHTCH NOT WORKING	مفتاح النافذه و الزجاج
10.C Dash Board	LEATHER REPLACED , PORTION WORN OUT	لوحة القيادة
10.D Sun Visor	BOTH SIDE MIRROR COVER PORTION DAMAGED , RIGHT SIDE MIRROR LIGHT NOT WORKING PROPERLY	حاجب الشمس
10.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.F Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae